


Vehicle details

VIN	WBA6V7100 05S84300	Brand	BMW	Maintenance date	-
Licence Plate	K5-65-JG	Model	2 Serie Gran Tourer 218i Corporate Executive 5d	Maintenance mileage	-
Registration date	08/01/2021	Year	2021	Exterior Color	Grey Metallic
Odometer	162 184 km	Engine size	1499	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	6		

Inspection Details

Inspection date	03/10/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
Sliding roof	✓
Panoramic roof	✓
Alloy wheel rims	✓
Heating seats	✓
Tow	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓


Removable element

Load cover	✓
------------	---

Technical Document

User manual	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Bridgestone 205/55/17 Summer 3.5 mm			Hankook 205/55/17 Summer 3.5 mm	
Hankook 205/55/17 Summer 4.0 mm			Hankook 205/55/17 Summer 4.0 mm	

Exterior

1



●●

Part	Alloy wheel 17"
Position	Front left
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

3



●●

Part	Alloy wheel 17"
Position	Back left
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

4



●●

Part	Bumper
Position	Back right
Damages	Scratched
Severity	-
Repair mode	Repair

5



●●

Part	Alloy wheel 17"
Position	Back right
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

6



●●

Part	Wing
Position	Back right
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

7



●●

Part	Door
Position	Back right
Damages	Scratched
Severity	-
Repair mode	Repair

8



●●●

Part	Alloy wheel 17"
Position	Front right
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

9



●●●

Part	Bumper
Position	Front
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

10



●●●●

Part	Bonnet
Position	-
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

Interior damage

2



Part	Interior cleaning
Position	Back
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning