



BMW 218i: K358JK

Vinnumber:	WBA6V710305S58113	Versionname:	218i 103kW Gran Tourer 5P
First Registrationdate:	16/01/2021	Fiscalpower:	
Expertise Mileage:	116927	Power Kw:	103
Bodytype:		Body colour:	Mineralgrau metallic
Gearbox:	MAN 6 VIT	Paint type:	Metallic
Transmission:	Front	Type of rims (mounted):	Aluminium
Fueltype:	Petrol	Parking lot:	408
Number of seats:	5		
Type of rims (mounted):	Aluminium		
Maintenance needed:	Yes		

Options

Number of keys total	2	Telephone equipment
GPS		Central consol F
Autom climate control		Luggage cover
Windows electric F		Headlights Xenon/LED/Laser
Radio multimedia		Rear parking sensors

Degree of wear

205/60/16/96 W				
Summer tyres:	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 5 mm
	Re.L.	Bridgestone: 5,5 mm	Re.R.	Bridgestone: 5,5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.5
Tyre profile depth RR				5.5
Tyre size FL				205/60 R 16 96 W
Tyre size FR				205/60 R 16 96 W
Tyre size RL				205/60 R 16 96 W
Tyre size RR				205/60 R 16 96 W
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				255
Tyre make FR				255
Tyre make RL				255
Tyre make RR				255

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Service, Maintenance, Execute



Alloy rim FL, Scratch(es), Repair and paint (complete)




Door FL, Scratch(es), Repair and paint (complete)




Wing RL, Scratch(es), Repair and paint (complete)



Windscreen, Stone chip(s), Windscreen repair



Alloy rim RR, Scratch(es), Repair and paint (complete)



Wing RR, Bad repair, Repair and paint (complete)



Door RR, Scratch(es), Repair and paint (complete)



Door FR, Scratch(es), Repair and paint (complete)



Rear window, Scratch(es), Replace



Bumper R, Scratch(es), Repair and paint (complete)



Bodywork, Paint measurement, Check

