



BMW 218i: H591NB

Vinnnummer:	WBA6V710405R32267	Versionname:	218iA 100kW Corporate Exective GT
First Registrationdate:	11/03/2020	Fiscalpower:	
Expertise Mileage:	188386	Power Kw:	100
Bodytype:		Body colour:	Glaciersilber Metallic
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Type of rims (mounted):	Aluminium
Fueltype:	Petrol	Parking lot:	439
Number of seats:	5		
Type of rims (mounted):	Aluminium		
Maintenance needed:	No		

Options

Number of keys total	2	Telephone equipment
GPS		Lining leather
Autom climate control		Central consol F
Windows electric F		Luggage cover
Radio multimedia		Headlights Xenon/LED/Laser
Keys removable towhook		Front parking sensors
		Rear parking sensors
		Tow bar removable

Degree of wear

205/55/17/95 W			
Summer tyres:	Fr.L.	Bridgestone: 5,9 mm	Fr.R. Bridgestone: 4,9 mm
	Re.L.	Bridgestone: 6,5 mm	Re.R. Bridgestone: 6,3 mm
Tyre profile depth FL			5.9
Tyre profile depth FR			4.9
Tyre profile depth RL			6.5
Tyre profile depth RR			6.3
Tyre size FL			205/55 R 17 95 W
Tyre size FR			205/55 R 17 95 W
Tyre size RL			205/55 R 17 95 W
Tyre size RR			205/55 R 17 95 W
Tyre type FL			Summer
Tyre type FR			Summer
Tyre type RL			Summer
Tyre type RR			Summer
Tyre make FL			255
Tyre make FR			255
Tyre make RL			255
Tyre make RR			255

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Bumper F, Dent(s) and scratch(es), Repair and paint (complete)





Bonnet, Dent(s), Repair and paint (complete)



Wing RR, Dent(s) and scratch(es), Repair and paint (complete)



Door RR, Bad repair, Repair and paint (complete)



Bumper R, Scratch(es), Repair and paint (complete)



Bumper RM, Dent(s) and scratch(es), Replace and paint



Bumper moulding R, Dent(s) and scratch(es), Replace



Bodywork, Paint measurement, Acceptable

