




BMW 2 GRAN TOURER: 1XSK779			
Vinnnumber:	WBA6W510405R56392	Versionname:	216d (85kW)
First Registrationdate:	4/05/2020	Fiscalpower:	
Expertise Mileage:	144229	Power Kw:	85
Bodytype:		Body colour	Blue
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:		Parking lot	2709
Fueltype:	Diesel		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Options			
Number of keys total	2	Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Seats F heated		Type of Tow bar	Tow bar removable
Radio multimedia			
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining artificial leather		
Type of climate control	Autom climate control		
Limited Technical Inspection			
Tyres			
	205/60/16/92 H		
Summer tyres:	Fr.L.	Continental: 5 mm	Fr.R.
	Re.L.	Michelin: 5 mm	Re.R.
Tyre profile depth FL			5.0
Tyre profile depth FR			5.0
Tyre profile depth RL			5.0
Tyre profile depth RR			5.0
Tyre size FL			205/60 R 16 92 H
Tyre size FR			205/60 R 16 92 H
Tyre size RL			205/60 R 16 92 H
Tyre size RR			205/60 R 16 92 H
Tyre type FL			Summer
Tyre type FR			Summer
Tyre type RL			Summer
Tyre type RR			Summer
Tyre make FL			256
Tyre make FR			256
Tyre make RL			261
Tyre make RR			261
Assistance equipment			
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		
Total cost ex VAT			1062,10
Seat cover FL, Damaged, Acceptable			0,00



Bonnet, Dent(s), Paintless dent repair	93,06
--	-------



Step L, Scratch(es), Acceptable	0,00
---------------------------------	------



Alloy rim RL, Scratch(es), Repair and paint (complete)	129,66
--	--------



Alloy rim FL, Scratch(es), Repair and paint (complete)	129,66
--	--------



Bumper R, Scratch(es), Repair and paint (complete)	289,07
--	--------



Tailgate / Boot, Scratch(es), Acceptable	0,00
--	------



Alloy rim FR, Scratch(es), Acceptable	0,00
---------------------------------------	------



Door RR, Dent(s) and scratch(es), Acceptable	0,00
--	------



Wing RR, Scratch(es), Repair and paint (complete)	420,65
---	--------

