



BMW 2 GRAN TOURER: 1YHJ348				
Vinnumber:	WBA6W510405S28281	Versionname:	216d (85kW)	
First Registrationdate:	1/09/2020	Fiscalpower:		
Expertise Mileage:	116175	Power Kw:	85	
Bodytype:		Body colour	Grey	
Gearbox:	Automatic	Type of rims (mounted)	Aluminium	
Transmission:		Parking lot	1721	
Fueltype:	Diesel			
Type of rims (mounted)	Aluminium			
Certificate of Conformity	Yes			
Category	Passenger Car			
Registration Certificate Car (BE)	Yes			
Registration Certificate Home (BE)	No			
Options				
Number of keys total	2	Sun Roof electric		
Cruise Control		Panoramic roof		
Steering wheel multifunctional		Luggage cover		
Seats F heated		Front parking sensors		
Radio multimedia		Rear parking sensors		
Type of headlighting	Headlighting LED	Type of Tow bar	No Tow bar	
Type of GPS	GPS big screen color			
Type of Lining	Lining leather			
Type of climate control	Autom climate control			
Limited Technical Inspection				
Tyres				
Summer tyres:	205/55/17/95 W			
	Fr.L.	BF Goodrich: 4 mm	Fr.R.	BF Goodrich: 3 mm
	Re.L.	Bridgestone: 4 mm	Re.R.	Bridgestone: 3 mm
Tyre profile depth FL			4.0	
Tyre profile depth FR			3.0	
Tyre profile depth RL			4.0	
Tyre profile depth RR			3.0	
Tyre size FL			205/55 R 17 95 W	
Tyre size FR			205/55 R 17 95 W	
Tyre size RL			205/55 R 17 95 W	
Tyre size RR			205/55 R 17 95 W	
Tyre type FL			Summer	
Tyre type FR			Summer	
Tyre type RL			Summer	
Tyre type RR			Summer	
Tyre make FL			2485	
Tyre make FR			2485	
Tyre make RL			255	
Tyre make RR			255	
Assistance equipment				
Number of charging cables (normal)	0			
Number of charging cables (rapid charge)	0			
Total cost ex VAT			1683,59	
Air vent, mid-dashboard, Broken, Replace			42,18	




Interior, Worn, Acceptable

0,00



Roof liner, Stain, Cleaning

28,43



Bumper F, Scratch(es), Repair and paint (complete)

289,07




Windscreen, Stone chip(s), Replace

0,00



Alloy rim RL polished, Scratch(es), Repair and paint (complete)

199,04



Wing RL, Scratch(es), Acceptable

0,00



Door FL, Scratch(es), Acceptable

0,00



Alloy rim FL polished, Scratch(es), Repair and paint (complete)

199,04



Bumper R, Scratch(es), Repair and paint (complete)

289,07



Boot lid covering R, Scratch(es), Replace

124,94



Boot lid covering R, Scratch(es), Smart repair

113,74



Internal boot lining R, Scratch(es), Acceptable

0,00



Alloy rim FR polished, Scratch(es), Repair and paint (complete)

199,04



Alloy rim RR polished, Scratch(es), Repair and paint (complete)

199,04





Step R, Chemical polution, Acceptable

0,00

