



BMW 2-Reeks Gran Tourer (UKL): 2ABD225

Vinnumber:	WBA6W910705T05801	Versionname:	218d Gran Tourer (F46) 2.0d 136pk/cv 5p
First Registrationdate:	5/02/2021	Fiscalpower:	
Expertise Mileage:	187168	Power Kw:	100
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:			
Maintenance	OK		
Maintenance	in 12000 km		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Type of Tow bar	Tow bar removable
GPS			
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

205/55/17/95 W				
Summer tyres:	Fr.L.	Bridgestone: 3 mm	Fr.R.	Bridgestone: 3 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm
Tyre profile depth FL	3.0			
Tyre profile depth FR	3.0			
Tyre profile depth RL	5.0			
Tyre profile depth RR	5.0			
Tyre size FL	205/55 R 17 95 W			
Tyre size FR	205/55 R 17 95 W			
Tyre size RL	205/55 R 17 95 W			
Tyre size RR	205/55 R 17 95 W			
Tyre type FL	Summer			
Tyre type FR	Summer			
Tyre type RL	Summer			
Tyre type RR	Summer			
Tyre make FL	255			
Tyre make FR	255			
Tyre make RL	255			
Tyre make RR	255			

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Seat cover FL, Stain, Acceptable



Bumper F, Scratch(es), Acceptable



Tyre FL, Worn, Check



Alloy rim RL, Scratch(es), Repair and paint (complete)



Door RL, Dent(s), Paintless dent repair



Luggage compartment cover, Missing, Replace



Tyre repair kit, Missing, Check



Bumper R, Dent(s) and scratch(es), Repair and paint (complete)



Alloy rim FR, Scratch(es), Repair and paint (complete)



Tyre FR, Worn, Check



Wing RR, Dent(s), Paintless dent repair



Sill trim R, Scratch(es), Repair and paint (complete)



Bodywork, Paint measurement, Acceptable



Bodywork, Not original part, Remove lettering

