



## BMW 2-Reeks Active Tourer (UKL): 1YXU411

|                                   |                          |                        |                                                        |
|-----------------------------------|--------------------------|------------------------|--------------------------------------------------------|
| Vinnumber:                        | <b>WBA6Y310007G77964</b> | Versionname:           | <b>225xe Active Tourer (F45) 1.5i 136pk/cv 5p Aut.</b> |
| First Registrationdate:           | <b>26/01/2021</b>        | Fiscalpower:           |                                                        |
| Expertise Mileage:                | <b>132733</b>            | Power Kw:              | <b>100</b>                                             |
| Bodytype:                         |                          | Type of rims (mounted) | <b>Aluminium</b>                                       |
| Gearbox:                          | <b>Automatic</b>         |                        |                                                        |
| Transmission:                     |                          |                        |                                                        |
| Fueltype:                         |                          |                        |                                                        |
| Maintenance                       | <b>OK</b>                |                        |                                                        |
| Maintenance                       | <b>dans 23000km</b>      |                        |                                                        |
| Battery functioning               | <b>Yes</b>               |                        |                                                        |
| Type of rims (mounted)            | <b>Aluminium</b>         |                        |                                                        |
| Certificate of Conformity         | <b>Yes</b>               |                        |                                                        |
| Category                          | <b>Passenger Car</b>     |                        |                                                        |
| Registration Certificate Car (BE) | <b>Yes</b>               |                        |                                                        |

## Options

|                          |                            |                 |                   |
|--------------------------|----------------------------|-----------------|-------------------|
| Number of keys total     | <b>2</b>                   | Luggage cover   |                   |
| GPS                      |                            | Type of Tow bar | <b>No Tow bar</b> |
| Type of Maintenance book | <b>Digital maintenance</b> |                 |                   |
| Type of GPS storage      | <b>HD</b>                  |                 |                   |


## Tyres

|                       |                       |                          |       |                          |
|-----------------------|-----------------------|--------------------------|-------|--------------------------|
|                       | <b>205/55/17/95 W</b> |                          |       |                          |
| Summer tyres:         | Fr.L.                 | <b>Bridgestone: 5 mm</b> | Fr.R. | <b>Bridgestone: 5 mm</b> |
|                       | Re.L.                 | <b>Bridgestone: 6 mm</b> | Re.R. | <b>Bridgestone: 5 mm</b> |
| Tyre profile depth FL |                       |                          |       | <b>5.0</b>               |
| Tyre profile depth FR |                       |                          |       | <b>5.0</b>               |
| Tyre profile depth RL |                       |                          |       | <b>6.0</b>               |
| Tyre profile depth RR |                       |                          |       | <b>5.0</b>               |
| Tyre size FL          |                       |                          |       | <b>205/55 R 17 95 W</b>  |
| Tyre size FR          |                       |                          |       | <b>205/55 R 17 95 W</b>  |
| Tyre size RL          |                       |                          |       | <b>205/55 R 17 95 W</b>  |
| Tyre size RR          |                       |                          |       | <b>205/55 R 17 95 W</b>  |
| Tyre type FL          |                       |                          |       | <b>Summer</b>            |
| Tyre type FR          |                       |                          |       | <b>Summer</b>            |
| Tyre type RL          |                       |                          |       | <b>Summer</b>            |
| Tyre type RR          |                       |                          |       | <b>Summer</b>            |
| Tyre make FL          |                       |                          |       | <b>255</b>               |
| Tyre make FR          |                       |                          |       | <b>255</b>               |
| Tyre make RL          |                       |                          |       | <b>255</b>               |
| Tyre make RR          |                       |                          |       | <b>255</b>               |

## Assistance equipment

|                                          |          |
|------------------------------------------|----------|
| Number of charging cables (normal)       | <b>2</b> |
| Number of charging cables (rapid charge) | <b>1</b> |

Interior covering A pillar L, Burned, Replace



Seat cover FL, Worn, Acceptable



Bumper F, Dent(s) and scratch(es), Repair and paint (complete)




Bumper moulding F, Scratch(es), Replace



Bumper moulding F, Scratch(es), Replace



Mirror side repeater L, Waterinfiltration, Replace



Outside rear-view mirror housing L, Scratch(es), Acceptable



Alloy rim FL, Scratch(es), Repair and paint (complete)



Door FL, Scratch(es), Acceptable



Door RL, Dent(s) and scratch(es), Repair and paint (complete)



Alloy rim RL, Scratch(es), Repair and paint (complete)



Wing RL, Dent(s) and scratch(es), Acceptable



Luggage compartment cover, Incomplete, Forfeit



Tailgate / Boot, Scratch(es), Acceptable



Bumper R, Scratch(es), Repair and paint (complete)



Alloy rim RR, Deformed / Strained, Replace





Alloy rim FR, Scratch(es), Repair and paint (complete)



Door RR, Scratch(es), Acceptable



Wing RR, Dent(s) and scratch(es), Repair and paint (complete)



Door FR, Scratch(es), Acceptable



Bodywork, Paint measurement, Acceptable

