



# BMW X1: 2BDU752

Vinnumber:	WBA71AB0205U28926	Versionname:	X1 xDrive25e (162 kW) (PHEV) 162kW/220pk 5D/P
First Registrationdate:	14/10/2021	Fiscalpower:	Auto-6
Expertise Mileage:	81998	Power Kw:	
Bodytype:		Body colour	Black
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:	4 Wheel-drive	Parking lot	d363
Fueltype:	Hybrid Petrol		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Bodywork	Clean		
Interior	Clean		

## Options

Number of keys total	2	Radio
Number keys remote	2	Lining leather
Windows electric F		Front parking sensors
Windows electric R		Rear parking sensors
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Navigation with screen		
Airco electronic		
Rims alloy		

## Limited Technical Inspection

Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Transmission	OK

## Degree of wear

225/55/17/97 H				
Winter tyres:	Fr.L.	Continental: 3 mm	Fr.R.	Continental: 3 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm
Tyre profile depth FL		3.0		
Tyre profile depth FR		3.0		
Tyre profile depth RL		4.0		
Tyre profile depth RR		4.0		
Tyre size FL		225/55 R 17 97 H		
Tyre size FR		225/55 R 17 97 H		
Tyre size RL		225/55 R 17 97 H		
Tyre size RR		225/55 R 17 97 H		
Tyre type FL		Winter		
Tyre type FR		Winter		
Tyre type RL		Winter		
Tyre type RR		Winter		
Tyre make FL		256		
Tyre make FR		256		
Tyre make RL		256		
Tyre make RR		256		

## Assistance equipment

Repair kit	No	Compressor	No
Number of charging cables (normal)	0		

Backrest cover RL, Scratch(es), Smart repair



Backrest cover FR, Scratch(es), Smart repair



Bumper spoiler F, Scratch(es), Smart repair




Bumper spoiler F, Scratch(es), Smart repair



Alloy rim RL, Scratch(es), Repair and paint (complete)




Wing RL, Bad repair, Check



Door RL, Scratch(es), Polish



Roof pillar L, Dent(s), Paintless dent repair



Alloy rim FL, Scratch(es), Repair and paint (complete)





Composite repair kit, max. 1 m<sup>2</sup>, Missing, Replace




Compressor, Missing, Replace



Charging cable (normal), Missing, Replace



Boot lid covering R, Scratch(es), Smart repair



Wing FR, Dent(s), Acceptable



Outside rear-view mirror base R, Scratch(es), Smart repair



Door FR, Dent(s), Paintless dent repair



Door RR, Scratch(es), Polish



Wing RR, Dent(s) and scratch(es), Acceptable



Roof, Bad repair, Check

