



BMW X1: 1YUN611			
Vinnumber:	WBA71AB0405S90757	Versionname:	xDrive25e (162 kW)
First Registrationdate:	18/12/2020	Fiscalpower:	
Expertise Mileage:	87527	Power Kw:	162
Bodytype:		Body colour:	Grey
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	2309
Fueltype:	Hybrid Petrol		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		

Options			
Number of keys total:	2	Seats electric F L:	
Cruise Control:		Luggage cover:	
Steering wheel multifunctional:		Front parking sensors:	
Seats F heated:		Rear parking sensors:	
Radio multimedia:		Type of Tow bar:	No Tow bar
Type of headlighting:	Headlighting LED		
Type of GPS:	GPS big screen color		
Type of Lining:	Lining fabrics		
Type of climate control:	Autom climate control		

Limited Technical Inspection

Degree of wear

225/55/17/92 H				
Winter tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				225/55 R 17 92 H
Tyre size FR				225/55 R 17 92 H
Tyre size RL				225/55 R 17 92 H
Tyre size RR				225/55 R 17 92 H
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				256
Tyre make FR				256
Tyre make RL				256
Tyre make RR				256

Assistance equipment

Number of charging cables (normal):	1	
Number of charging cables (rapid charge):	1	
Total cost ex VAT		2496,89
Seat cover FL, Stain, Cleaning		28,43



Seat cover R, Stain, Cleaning

28,43



Seat cover FR, Stain, Cleaning

28,43



Dashboard, Scratch(es), Acceptable

0,00



Bumper F, Scratch(es), Acceptable

0,00



Bonnet, Chemical polution, Acceptable

0,00



Door FL, Dent(s), Repair and paint (complete)

492,50



Alloy rim RL, Scratch(es), Acceptable

0,00



Wing trim RL, Scratch(es), Acceptable

0,00



Bumper R, Scratch(es), Repair and paint (complete)

289,07




Tailgate / Boot, Dent(s), Acceptable

0,00



Rear window, Scratch(es), Replace

552,20



Bumper trim R, Scratch(es), Acceptable

0,00



Door FR, Dent(s), Acceptable

0,00



Door RR, Scratch(es), Acceptable

0,00



Wing RR, Scratch(es), Repair and paint (complete)

420,65



Alloy rim FR, Scratch(es), Acceptable

0,00



Wing trim RR, Scratch(es), Acceptable

0,00



Roof, Chemical polution, Repair and paint (complete)

657,18



Door FL, Scratch(es), Acceptable

0,00

