MAC△DAM

BMW X1: 2AJS298

Vinnumber:	WBA71AB0905T56011	Versionname:	xDrive25e (162 kW)
First Registrationdate:	19/04/2021	Fiscalpower:	
Expertise Mileage:	73079	Power Kw:	
Bodytype:		Body colour	Black
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:		Parking lot	1408
Fueltype:	Hybrid Petrol		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Registration Certificate Home (BE)	No		

Options

Number of keys total	2	Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Seats F heated		Type of Tow bar	No Tow bar
Radio multimedia			
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Tyres

	225/55/17/97 W			
Summer tyres:	Fr.L.	Uniroyal: 4 mm	Fr.R.	Uniroyal: 4 mm
	Re.L.	Pirelli: 3 mm	Re.R.	Pirelli: 2 mm

Tyre profile depth FL	4.0
Tyre profile depth FR	4.0
Tyre profile depth RL	3.0
Tyre profile depth RR	2.0
Tyre size FL	225/55 R 17 97 W
Tyre size FR	225/55 R 17 97 W
Tyre size RL	225/55 R 17 97 W
Tyre size RR	225/55 R 17 97 W
Tyre type FL	Summer
Tyre type FR	Summer
Tyre type RL	Summer
Tyre type RR	Summer
Tyre make FL	265
Tyre make FR	265
Tyre make RL	264
Tyre make RR	264

Assistance equipment

Number of charging cables (normal)	1
Number of charging cables (rapid charge)	1

Total cost ex VAT	**491,11**
Interior, Worn, Acceptable	**0,00**

| **Bumper F, Scratch(es), Acceptable** | **0,00** |

| **Bumper spoiler F, Scratch(es), Acceptable** | **0,00** |

| **Bonnet, Chemical polution, Polish** | **0,00** |

| **Windscreen, Stone chip(s), Acceptable** | **0,00** |

| **Door FL, Scratch(es), Acceptable** | **0,00** |

| **Door RL, Scratch(es), Acceptable** | **0,00** |

| **Bumper R, Scratch(es), Repair and paint (complete)** | **289,07** |

| **Bumper trim R, Scratch(es), Replace** | **202,04** |

Door FR, Scratch(es), Acceptable | **0,00**

Roof, Chemical polution, Polish | **0,00**