

**BMW X1: 2AVS883**

Vinnumber:	WBA71AC0005U01979	Versionname:	
First Registrationdate:	6/08/2021	Fiscalpower:	
Expertise Mileage:	99388	Power Kw:	100
Bodytype:		Parking lot	2820
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:		Body colour	Black
Fueltype:	Diesel		
Certificate of Conformity	Yes		
Type of rims (mounted)	Aluminium		
Category	Passenger Car		
Registration Certificate Home (BE)	No		
Registration Certificate Car (BE)	Yes		

Options

Radio multimedia		Luggage cover	
Steering wheel multifunctional		Rear parking sensors	
Seats F heated		Front parking sensors	
Type of GPS	GPS big screen color	Type of Tow bar	No Tow bar
Cruise Control			
Type of climate control	Autom climate control		
Number of keys total	2		
Type of headlighting	Headlighting Halogen		
Type of Lining	Lining artificial leather		

Limited Technical Inspection**Tyres**

Tyre size RL	225/55 R 17 97 H
Tyre type FL	Winter
Tyre type RL	Winter
Tyre profile depth FR	4.0
Tyre profile depth RR	4.0
Tyre make FR	2480
Tyre size FR	225/55 R 17 97 H
Tyre make RR	2480
Tyre size RR	225/55 R 17 97 H

225/55/17/97 H

Winter tyres:	Fr.L.	Vredestein: 4 mm	Fr.R.	Vredestein: 4 mm
	Re.L.	Vredestein: 4 mm	Re.R.	Vredestein: 4 mm

Tyre profile depth FL	4.0
Tyre make FL	2480
Tyre size FL	225/55 R 17 97 H
Tyre type FR	Winter
Tyre profile depth RL	4.0
Tyre type RR	Winter
Tyre make RL	2480

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Total cost ex VAT	684,97
Bonnet, Chemical polution, Repair and paint (complete)	395,90



Bumper F, Scratch(es), Acceptable 0,00



Door FL, Scratch(es), Acceptable 0,00



Wing RL, Scratch(es), Acceptable 0,00



Bumper R, Scratch(es), Repair and paint (complete) 289,07



Tailgate / Boot, Scratch(es), Acceptable 0,00



Door RR, Scratch(es), Acceptable 0,00



Door FR, Scratch(es), Acceptable 0,00



Wing RR, Scratch(es), Acceptable 0,00

