



BMW X1 (UKL): 2BCU969

Vinnumber:	WBA71AC0205U29959	Versionname:	X1 (F48) 18d sDrive 2.0d 150pk/cv 5p Aut.
First Registrationdate:	5/10/2021	Fiscalpower:	
Expertise Mileage:	183417	Power Kw:	110
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:			
Maintenance	NOT OK		
Maintenance	sinds 900km		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	No Tow bar
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

225/55/17/101 Y			
Summer tyres:	Fr.L.	Continental: 5 mm	Fr.R.
	Re.L.	Goodyear: 5 mm	Re.R.
Tyre profile depth FL			5.0
Tyre profile depth FR			6.0
Tyre profile depth RL			5.0
Tyre profile depth RR			5.0
Tyre size FL			225/55 R 17 101 Y
Tyre size FR			225/55 R 17 101 Y
Tyre size RL			225/55 R 17 97 W
Tyre size RR			225/55 R 17 97 W
Tyre type FL			Summer
Tyre type FR			Summer
Tyre type RL			Summer
Tyre type RR			Summer
Tyre make FL			256
Tyre make FR			256
Tyre make RL			259
Tyre make RR			259

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Service, Maintenance, Check



Instrument panel, complete, Not functioning (well), Check



Interior covering A pillar L, Scratch(es), Acceptable



Backrest cover FL, Scratch(es), Acceptable



Backrest cover FR, Scratch(es), Acceptable



Bonnet, Scratch(es), Acceptable



Door RL, Dent(s) and scratch(es), Spot repair



Door FL, Dent(s) and scratch(es), Spot repair



Step L, Scratch(es), Acceptable



Internal boot lining R, Scratch(es), Acceptable



Boot lid covering R, Scratch(es), Acceptable



Bumper moulding R, Scratch(es), Acceptable



Bumper trim R, Scratch(es), Acceptable




Alloy rim RR, Scratch(es), Acceptable



Door RR, Dent(s), Acceptable



Door FR, Scratch(es), Acceptable



Bodywork, Paint measurement, Acceptable

