



BMW X1 (UKL): 1WRU907

Vinnumber:	WBA71AC0605P23526	Versionname:	X1 (F48) 18d sDrive 2.0d 136pk/cv 5p Aut.
First Registrationdate:	26/08/2019	Fiscalpower:	
Expertise Mileage:	144411	Power Kw:	100
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:			
Maintenance	NOT OK		
Maintenance	augustus 2025		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	No Tow bar
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

225/55/17/101 Y				
Summer tyres:	Fr.L.	Fulda: 5 mm	Fr.R.	Fulda: 5 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				225/55 R 17 101 Y
Tyre size FR				225/55 R 17 101 Y
Tyre size RL				225/55 R 17 97 W
Tyre size RR				225/55 R 17 97 W
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				2484
Tyre make FR				2484
Tyre make RL				259
Tyre make RR				259

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Service, Maintenance, Check



Seat cover FL, Worn, Check



Backrest cover FL, Scratch(es), Acceptable



Backrest cover FR, Scratch(es), Smart repair




Bumper F, Scratch(es), Repair and paint (complete)



Alloy rim FL, Scratch(es), Repair and paint (complete)




Wing trim FL, Scratch(es), Replace



Wing FL, Scratch(es), Acceptable



Outside rear-view mirror housing L, Scratch(es), Acceptable



Outside rear-view mirror base L, Broken, Replace



Mirror side repeater L, Waterinfiltration, Replace



Door FL, Dent(s) and scratch(es), Repair and paint (complete)




Roof pillar L, Scratch(es), Acceptable



Door RL, Dent(s) and scratch(es), Repair and paint (complete)



Outer door handle RL, Scratch(es), Acceptable



Wing RL, Dent(s) and scratch(es), Acceptable



Rear bulkhead lining, Scratch(es), Acceptable



Boot lid covering R, Scratch(es), Acceptable



Tailgate / Boot, Scratch(es), Acceptable



Bumper R, Scratch(es), Repair and paint (complete)



Bumper trim R, Scratch(es), Replace



Bumper moulding R, Scratch(es), Repair and paint (complete)



Step R, Dent(s) and scratch(es), Spot repair



Outside rear-view mirror housing R, Scratch(es), Repair and paint (complete)



Mirror side repeater R, Waterinfiltration, Replace



Outside rear-view mirror base R, Scratch(es), Smart repair



Outer door handle FR, Scratch(es), Acceptable



Door FR, Scratch(es), Acceptable



Door RR, Scratch(es), Acceptable



Wing RR, Dent(s), Spot repair



Bodywork, Paint measurement, Acceptable

