



BMW X1 (UKL): 2ADK567

Vinnumber:	WBA71AC0705T32157	Versionname:	X1 (F48) 18d sDrive 2.0d 136pk/cv 5p Aut.
First Registrationdate:	1/03/2021	Fiscalpower:	
Expertise Mileage:	170862	Power Kw:	100
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:			
Maintenance	OK		
Maintenance	2400 km - 01/2027		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	Tow bar removable
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

	225/50/18/95 H			
Winter tyres:	Fr.L.	Bridgestone: 2 mm	Fr.R.	Bridgestone: 2 mm
	Re.L.	Bridgestone: 6 mm	Re.R.	Bridgestone: 6 mm
Tyre profile depth FL				2.0
Tyre profile depth FR				2.0
Tyre profile depth RL				6.0
Tyre profile depth RR				6.0
Tyre size FL				225/50 R 18 95 H
Tyre size FR				225/50 R 18 95 H
Tyre size RL				225/50 R 18 95 H
Tyre size RR				225/50 R 18 95 H
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				255
Tyre make FR				255
Tyre make RL				255
Tyre make RR				255

Assistance equipment

Number of charging cables (normal)	0	Runflat	Yes
Number of charging cables (rapid charge)	0		

Seat cover FL, Worn, Acceptable



Floor covering FL, Worn, Acceptable



Bonnet, Stone chip(s), Acceptable



Bumper F, Scratch(es), Acceptable



Alloy rim FL, Scratch(es), Repair and paint (complete)



Door FL, Scratch(es), Acceptable



Door RL, Scratch(es), Acceptable



Step L, Scratch(es), Acceptable



Wing RL, Dent(s), Acceptable



Alloy rim RL, Scratch(es), Acceptable



Boot lid covering R, Scratch(es), Acceptable



Bumper R, Scratch(es), Acceptable



Door RR, Scratch(es), Acceptable



Step R, Scratch(es), Acceptable



Door FR, Dent(s) and scratch(es), Acceptable



Alloy rim FR, Scratch(es), Acceptable



Bodywork, Paint measurement, Acceptable

