



BMW X1 (UKL): 2BLE797

Vinnumber:	WBA71AC0805U74579	Versionname:	X1 (F48) 18d sDrive 2.0d 136pk/cv 5p Aut.
First Registrationdate:	3/01/2022	Fiscalpower:	
Expertise Mileage:	181026	Power Kw:	100
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:			
Maintenance	OK		
Maintenance	dans 3600 km		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	No Tow bar
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

	225/55/17/97 H			
Winter tyres:	Fr.L.	Goodyear: 3 mm	Fr.R.	Goodyear: 3 mm
	Re.L.	Goodyear: 3 mm	Re.R.	Goodyear: 3 mm
Tyre profile depth FL				3.0
Tyre profile depth FR				3.0
Tyre profile depth RL				3.0
Tyre profile depth RR				3.0
Tyre size FL				225/55 R 17 97 H
Tyre size FR				225/55 R 17 97 H
Tyre size RL				225/55 R 17 97 H
Tyre size RR				225/55 R 17 97 H
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				259
Tyre make FR				259
Tyre make RL				259
Tyre make RR				259

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Seat cover FL, Worn, Acceptable



Door panel RL, Scratch(es), Smart repair



Windscreen, Stone chip(s), Windscreen repair



Door FL, Scratch(es), Acceptable



Wing trim RL, Scratch(es), Acceptable



Wing RL, Dent(s), Acceptable



Boot carpet, Stain, Cleaning



Boot lid covering R, Scratch(es), Replace



Luggage compartment cover, Incomplete, Forfeit



Bumper R, Scratch(es), Repair and paint (complete)



Wing RR, Scratch(es), Acceptable



Door RR, Scratch(es), Repair and paint (complete)



Door FR, Dent(s) and scratch(es), Acceptable



Alloy rim FR, Scratch(es), Acceptable



Tyre FR, Worn, Check



Bodywork, Paint measurement, Acceptable

