



BMW X1: 1XKD075

Vinnumber:	WBA71AC0X05P77122	Versionname:	X1 sDrive18d (100 kW) 100kW/136pk 5D/P Man-6
First Registrationdate:	22/01/2020	Fiscalpower:	
Expertise Mileage:	77758	Power Kw:	
Bodytype:		Body colour:	Grey
Gearbox:	MAN 6 VIT	Type of rims (mounted):	Aluminium
Transmission:	Front	Parking lot:	b615
Fueltype:	Diesel		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Bodywork:	Clean		
Interior:	Clean		

Options

Number of keys total:	2	Radio
Number keys remote:	2	Front parking sensors
GPS storage:		Rear parking sensors
GPS storage:	HD	
Windows electric F:		
Windows electric R:		
Cruise Control:		
Steering wheel multifunctional:		
Navigation with screen:		
Airco electronic:		
Rims alloy:		








Limited Technical Inspection

Airco functioning:	Yes	Sound engine:	OK
Idle position:	OK	Clutch test:	OK
Engine startingtime:	OK	Transmission:	OK
Exhaust gass:	OK		

Degree of wear

225/55/17/101 V				
Winter tyres:	Fr.L.	Vredestein: 4 mm	Fr.R.	Vredestein: 4 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				225/55 R 17 101 V
Tyre size FR				225/55 R 17 97 H
Tyre size RL				225/55 R 17 101 V
Tyre size RR				225/55 R 17 97 H
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				2480
Tyre make FR				2480
Tyre make RL				256
Tyre make RR				256

Assistance equipment

Repair kit	No	Compressor	No
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		
Interior, Worn, Acceptable			
			
Door panel RL, Scratch(es), Acceptable			
			
Interior, Dirty, Cleaning			
			
Bumper F, Scratch(es), Repair and paint (complete)			
			
Door FL, Dent(s), Acceptable			
			
Compressor, Missing, Replace			
			
Composite repair kit, max. 1 m², Missing, Replace			
			
Internal boot lining R, Broken, Forfeit			



Rear window, Scratch(es), Replace



Step R, Dent(s), Paintless dent repair

