



BMW 1-Reeks (UKL): 2BHM885

Vinnumber:	WBA7K310207K30460	Versionname:	118i (F40) 1.5i 136pk/cv 5p Aut.
First Registrationdate:	29/11/2021	Fiscalpower:	
Expertise Mileage:	73420	Power Kw:	100
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:			
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Battery functioning	Yes		
Registration Certificate Car (BE)	Yes		

Options

Type of Maintenance book	Digital maintenance	Luggage cover	
Type of GPS storage	HD	Type of Tow bar	No Tow bar
GPS			
Number of keys total	2		

Tyres

Tyre size RL	225/45 R 17 91 H
Tyre type FL	Winter
Tyre type RL	Winter
Tyre profile depth FR	4.0
Tyre profile depth RR	4.0
Tyre size FR	225/45 R 17 91 H
Tyre make FR	255

Winter tyres:	225/45/17/91 H			
	Fr.L.	Bridgestone: 4 mm	Fr.R.	Bridgestone: 4 mm
	Re.L.	Bridgestone: 4 mm	Re.R.	Bridgestone: 4 mm

Tyre size RR	225/45 R 17 91 H
Tyre make RR	255
Tyre profile depth FL	4.0
Tyre size FL	225/45 R 17 91 H
Tyre make FL	255
Tyre profile depth RL	4.0
Tyre type FR	Winter
Tyre type RR	Winter
Tyre make RL	255

Assistance equipment

Number of charging cables (normal)	0	Compressor	Yes
Number of charging cables (rapid charge)	0		
Repair kit	Yes		

Backrest cover FL, Scratch(es), Acceptable



Door panel RR, Worn, Forfeit



Alloy rim RL polished, Scratch(es), Replace




Door FL, Scratch(es), Acceptable



Alloy rim FL polished, Scratch(es), Acceptable



Wing RL, Scratch(es), Acceptable



Tailgate / Boot, Scratch(es), Acceptable




Bumper R, Scratch(es), Repair and paint (complete)



Door RR, Scratch(es), Repair and paint (complete)



Alloy rim RR polished, Scratch(es), Repair and paint (complete)



Alloy rim FR polished, Scratch(es), Repair and paint (complete)



Tyres, Out of tolerance, Check



Bodywork, Paint measurement, Acceptable

