



BMW 118i: J222FK

Vinnumber:	WBA7K310707G27181	Versionname:	118i 103kW (NEDC)
First Registrationdate:	20/07/2020	Fiscalpower:	
Expertise Mileage:	176162	Power Kw:	103
Bodytype:		Body colour	Schwarz II
Gearbox:	MAN 6 VIT	Paint type	Opaque
Transmission:	Back	Type of rims (mounted)	Aluminium
Fueltype:	Petrol	Parking lot	295
Number of seats	5		
Type of rims (mounted)	Aluminium		
Maintenance needed	Yes		

Options

Number of keys total	2	Telephone equipment
GPS		Lining semi-leather
Autom climate control		Central consol F
Windows electric F		Headlights Xenon/LED/Laser
Radio multimedia		Front parking sensors
		Rear parking sensors

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	225 / 45 / 17 / 94 / V / Aluminium	5,1 mm	Bridgestone	Winter
	Right	225 / 45 / 17 / 94 / V / Aluminium	4,7 mm	Bridgestone	Winter
Rear	Left	225 / 45 / 17 / 94 / V / Aluminium	6,2 mm	Bridgestone	Winter
	Right	225 / 45 / 17 / 94 / V / Aluminium	6,0 mm	Bridgestone	Winter

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Service, Maintenance, Execute



Door panel FL, Worn, Replace



Interior, Smell, Ozone treatment





Alloy rim FL, Scratch(es), Repair and paint (complete)



Door FL, Scratch(es), Repair and paint (complete)



Wing RL, Scratch(es), Repair and paint (complete)



Bonnet, Stone chip(s), Repair and paint (complete)



Bumper F, Dent(s) and scratch(es), Repair and paint (complete)



Grille frame, Scratch(es), Smart repair



Wing RR, Bad repair, Repair and paint (complete)



Door RR, Bad repair, Repair and paint (complete)



Boot cover, Missing, Replace



Bumper R, Scratch(es), Repair and paint (complete)



Tailgate / Boot, Scratch(es), Repair and paint (complete)



Bodywork, Paint measurement, Acceptable



Roof, Dent(s), Repair and paint (complete)

