



BMW 118i L170DH

Vinnnumber:	WBA7K310907J00935	Versionname:	118iA 100kW Private Lease M Sport Edition
First Registrationdate:	26/04/2021	Fiscalpower:	
Expertise Mileage:	157208	Power Kw:	100
Bodytype:		Body colour:	Mineralgrau metallic
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Type of rims (mounted):	Aluminium
Fueltype:	Petrol	Parking lot:	352
Number of seats:	5		
Type of rims (mounted):	Aluminium		
Maintenance needed:	Yes		

Options

Number of keys total	2	Telephone equipment
GPS		Lining semi-leather
Autom climate control		Sun Roof electric
Windows electric F		Panoramic roof
Radio multimedia		Central consol F
		Luggage cover
		Headlights Xenon/LED/Laser
		Front parking sensors
		Rear parking sensors

Degree of wear

225/40/18/92 Y				
Summer tyres:	Fr.L.	Bridgestone: 5,2 mm	Fr.R.	Bridgestone: 4,2 mm
	Re.L.	Bridgestone: 4,8 mm	Re.R.	Bridgestone: 5,2 mm
Tyre profile depth FL				5.2
Tyre profile depth FR				4.2
Tyre profile depth RL				4.8
Tyre profile depth RR				5.2
Tyre size FL				225/40 R 18 92 Y
Tyre size FR				225/40 R 18 92 Y
Tyre size RL				225/40 R 18 92 Y
Tyre size RR				225/40 R 18 92 Y
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				255
Tyre make FR				255
Tyre make RL				255
Tyre make RR				255


Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Service, Maintenance, Execute



Alloy rim FL, Scratch(es), Repair and paint (complete)



Alloy rim RL, Scratch(es), Repair and paint (complete)



Wing RL, Scratch(es), Repair and paint (complete)



Bumper F, Dent(s) and scratch(es), Repair and paint (complete)



Windscreen, Stone chip(s), Windscreen repair



Alloy rim FR, Scratch(es), Repair and paint (complete)



Door FR, Scratch(es), Repair and paint (complete)



Bodywork, Paint measurement, Acceptable

