



BMW SERIE 1: GD-540-AL

Vinnumber:	WBA7K310X07K26544	Versionname:	
First Registrationdate:	18/11/2021	Fiscalpower:	
Expertise Mileage:	112669	Power Kw:	
Bodytype:	Berline	Body colour:	Black
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Back	Interior colour:	Black
Fueltype:	Petrol	Type of rims (mounted):	Aluminium
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Category:	Passenger Car		

Options

Number of keys total	1	Luggage cover
Number keys remote	1	Rear view camera
GPS big screen color		

Tyres

225/40/18/92 (Y)				
Summer tyres:	Fr.L.	Pirelli: 50%	Fr.R.	Pirelli: 55%
	Re.L.	Pirelli: 30%	Re.R.	Pirelli: 35%
Tyre profile depth FL				4.8
Tyre profile depth FR				4.6
Tyre profile depth RL				6.2
Tyre profile depth RR				5.8
Tyre size FL				225/40 ZR 18 92 (Y)
Tyre size FR				225/40 ZR 18 92 (Y)
Tyre size RL				225/40 ZR 18 92 (Y)
Tyre size RR				225/40 ZR 18 92 (Y)
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				264
Tyre make FR				264
Tyre make RL				264
Tyre make RR				264

Assistance equipment

Repair kit	No	Compressor	No
Remote ignition key (no insert), Missing, Forfeit			



Seat cover RL, Stain, Cleaning



Tyres, No damage, Acceptable



Tyre FL, Tear, Replace



Alloy rim FL bitone/polychrome, Scratch(es), Repair/replace (lump sum)



[Damage Picture - 1](#)

Tyre RL, Tear, Replace



Alloy rim RR bitone/polychrome, Scratch(es), Repair/replace (lump sum)




Alloy rim FR bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Tyre FR, Tear, Replace



Door FL, Dent(s) and scratch(es), Repair and paint (complete)



Number plate F, Broken, Repair/replace (lump sum)



Roof pillar R, Dent(s), Repair and paint (complete)



Door FR, Scratch(es), Paint



Outside rear-view mirror housing R, Bad repair, Paint



Compressor, Missing, Repair/replace (lump sum)



Tyre repair kit, Missing, Repair/replace (lump sum)



Rubber seal for boot lid, Tear, Replace



Roof, Dent(s), Repair and paint (complete)

