



BMW 1-Reeks (UKL): 1YDB851

Vinnumber:	WBA7M710007G32188	Versionname:	116d (F40) 1.5d 116pk/cv 5p Aut.
First Registrationdate:	24/07/2020	Fiscalpower:	
Expertise Mileage:	145646	Power Kw:	85
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:			
Maintenance	OK		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	Tow bar removable
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

	205/55/16/91 W			
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 2 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 4 mm
Tyre profile depth FL				3.0
Tyre profile depth FR				2.0
Tyre profile depth RL				6.0
Tyre profile depth RR				4.0
Tyre size FL				205/55 R 16 91 W
Tyre size FR				205/55 R 16 91 W
Tyre size RL				205/55 R 16 91 W
Tyre size RR				205/55 R 16 91 W
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Seat cover FL, Stain, Cleaning



Seat cover R, Stain, Cleaning



Seat cover FR, Stain, Cleaning



Dashboard, Scratch(es), Acceptable



Bumper F, Scratch(es), Spot repair



Bumper F, Scratch(es), Acceptable



Windscreen, Repaired, Acceptable




Alloy rim FL, Scratch(es), Repair and paint (complete)



Outside rear-view mirror housing L, Scratch(es), Acceptable



Alloy rim RL, Scratch(es), Acceptable



Boot lid covering R, Scratch(es), Smart repair



Rear bulkhead lining, Scratch(es), Acceptable



Bumper R, Scratch(es), Repair and paint (complete)



Alloy rim RR, Scratch(es), Repair and paint (complete)



Door RR, Dent(s) and scratch(es), Acceptable



Alloy rim FR, Scratch(es), Repair and paint (complete)



Wing RR, Repaired, Check



Door RR, Repaired, Check



Wing RR, Scratch(es), Acceptable



Bodywork, Paint measurement, Acceptable

