



BMW 1 HATCH: 1YNL816

Vinnnumber:	WBA7M710207G98421	Versionname:	116d (85 kW)
First Registrationdate:	12/10/2020	Fiscalpower:	
Expertise Mileage:	122192	Power Kw:	85
Bodytype:		Parking lot	3123
Gearbox:	MAN 6 VIT	Type of rims (mounted)	Aluminium
Transmission:		Body colour	Black
Fueltype:	Diesel		
Certificate of Conformity	Yes		
Type of rims (mounted)	Aluminium		
Category	Passenger Car		
Registration Certificate Home (BE)	No		
Registration Certificate Car (BE)	Yes		
Maintenance	OK		
Maintenance	19000 km - 07/2027		

Options

Radio multimedia		Luggage cover	
Steering wheel multifunctional		Rear parking sensors	
Seats F heated		Front parking sensors	
Type of GPS storage	HD	Type of Tow bar	No Tow bar
Type of GPS	GPS big screen color		
Cruise Control			
Type of climate control	Autom climate control		
Number of keys total	2		
Type of headlighting	Headlighting LED		
Type of Lining	Lining fabrics		

Limited Technical Inspection

Tyres

Tyre size RL	205/55 R 16 91 W
Tyre type FL	Summer
Tyre type RL	Summer
Tyre profile depth FR	4.0
Tyre profile depth RR	6.0
Tyre make FR	261
Tyre size FR	205/55 R 16 91 W
Tyre make RR	261
Tyre size RR	205/55 R 16 91 W

205/55/16/91 W			
Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Tyre profile depth FL	4.0
Tyre make FL	261
Tyre size FL	205/55 R 16 91 W
Tyre type FR	Summer
Tyre profile depth RL	6.0
Tyre type RR	Summer
Tyre make RL	261

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Total cost ex VAT	0,00
Ignition key, Not functioning (well), Acceptable	0,00



Door panel FL, Worn, Acceptable 0,00



Bonnet, Stone chip(s), Acceptable 0,00



Door FL, Scratch(es), Acceptable 0,00



Wing FL, Dent(s) and scratch(es), Acceptable 0,00



Outer door handle RL, Scratch(es), Acceptable 0,00



Alloy rim RL, Scratch(es), Acceptable 0,00



Bumper R, Scratch(es), Acceptable 0,00



Tailgate / Boot, Scratch(es), Acceptable 0,00



Door RR, Dent(s) and scratch(es), Acceptable 0,00





Wing RR, Scratch(es), Acceptable 0,00



Alloy rim FR, Scratch(es), Acceptable 0,00



Roof, Dent(s), Acceptable 0,00

