



ARVAL
BNP PARIBAS GROUP

2CTX142

INSPECTION REPORT

End Of Contract


GENERAL INFO

File	265455
License plate	2CTX142
Vehicle identification number	WBA7M710307L72303
Dossier	2021264061
Make	BMW 116d 85kW Aut.
Mileage	54354.00
First registration	30/11/2022
	12/12/2024

CHECK POINTS

Description	Number	Present	Remark
Spare wheel		N	
Certificate of conformity		N	
Registration certificate		N	
Keys	2	Y	
Registration Part 2		N	
Repair kit		N	
RunOnFlat		N	
Charge back wrong tyres		N	
Original license plate		Y	
Towbar (+keys)		N	
Charging cable		N	





DAMAGES

Damages	Type	Acceptable
14	Bumper Front // Repair & Painting	N
271	Bumper Front / Trim Left / Replace	N
272	Bumper Front / Trim Right / Replace	N
18	Bumper Front / Spoiler / Replace	Y
35	Front Bonnet // Polish	Y
64	Wing Front Left // Repair & Painting	Y
71	Side View Mirror Left // Replace Not Painted	N
75	Side View Mirror Left // Painting	Y
125	Light / Rear Left On Rear Bonnet / Replace	Y
133	Bumper Rear // Repair & Painting	N
162	Roof // Painting	N
174	Light / Rear Right / Replace	Y
196	Door Rear Right // Polish	Y
222	Side View Mirror Right // Painting	Y
228	Side View Mirror Right / Direction Indicator / Replace	N
311	Wheel Alloy Front Left // Repair	N
331	Wheel Alloy Rear Right // Repair	N
341	Wheel Alloy Front Right // Repair	N
346	Tyre Front Right // Replace	N
850	Certificate of Conformity //	N
851	Registration Card //	N
860	Interior Cleaning // Small	N

Damage Pictures



Door Rear Right // Polish-scratch



Wheel Alloy Rear Right // Repair-scratch



Light / Rear Left On Rear Bonnet / Replace-scratch





Bumper Rear // Repair & Painting-scratch



Side View Mirror Left // Replace Not Painted-scratch



Wheel Alloy Front Left // Repair-scratch



Front Bonnet // Polish-scratch



Side View Mirror Left // Painting-scratch



Light / Rear Right / Replace-scratch



Wheel Alloy Front Right // Repair-scratch



Side View Mirror Right // Painting-scratch



Wing Front Left // Repair & Painting-scratch + dent




Bumper Front / Spoiler / Replace-scratch + dent






Side View Mirror Right / Direction Indicator / Replace-cracked



Tyre Front Right // Replace-tear



Interior Cleaning // Small-stain



Roof // Painting-scratch



Bumper Front // Repair & Painting-scratch + dent



Bumper Front / Trim Left / Replace-scratch



Bumper Front / Trim Right / Replace-scratch