

INSPECTION REPORT


End Of Contract

GENERAL INFO

File	279608
License plate	1XGV454
Vehicle identification number	WBA7M710605P99325
Dossier	2019291014
Make	BMW 116d 85kW Aut.
Mileage	122464.00
First registration	02/01/2020
	25/06/2025

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
14	Bumper Front // Repair & Painting	N
32	Front Bonnet // Painting	N
38	Front Bonnet / Insulation / Replace	N
72	Side View Mirror Left // Painting	N
113	Wing Rear Left // Painting	N
134	Bumper Rear // Repair & Painting	N
194	Door Rear Right // Repair & Painting	N
209	Rocker Panel Right / Cover / Replace	N
211	Door Front Right // Smart Repair Medium	N
310	Wheel Two Tone Front Left // Repair	N
320	Wheel Two Tone Rear Left // Repair	N
330	Wheel Two Tone Rear Right // Repair	N
340	Wheel Two Tone Front Right // Repair	N
346	Tyre Front Right // Replace	N
442	Seat Rear Central / Bottom Coating / Replace	N

Damage Pictures



Bumper Front // Repair & Painting-scratch



Front Bonnet // Painting-scratch





Wheel Two Tone Front Left // Repair-scratch



Side View Mirror Left // Painting-scratch



Wheel Two Tone Rear Left // Repair-scratch





Wing Rear Left // Painting-scratch



Wheel Two Tone Rear Right // Repair-scratch



Wheel Two Tone Front Right // Repair-scratch



Door Rear Right // Repair & Painting-dent




Door Front Right // Smart Repair Medium-scratch + dent



Rocker Panel Right / Cover / Replace-scratch + dent



Bumper Rear // Repair & Painting-scratch + dent



Tyre Front Right // Replace-tear



Seat Rear Central / Bottom Coating / Replace-worn



Front Bonnet / Insulation / Replace-hole