



BMW 1-Reeks (UKL): 2BBF387

Vinnumber:	WBA7M710607J72614	Versionname:	116d (F40) 1.5d 116pk/cv 5p
First Registrationdate:	17/09/2021	Fiscalpower:	
Expertise Mileage:	74835	Power Kw:	85
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	MAN 6 VIT		
Transmission:			
Fueltype:			
Maintenance	NOT OK		
Maintenance	dépassé de 4500 kn		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	No Tow bar
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

	205/55/16/91 H			
Winter tyres:	Fr.L.	Michelin: 2 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm
Tyre profile depth FL				2.0
Tyre profile depth FR				3.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				205/55 R 16 91 H
Tyre size FR				205/55 R 16 91 H
Tyre size RL				205/55 R 16 91 H
Tyre size RR				205/55 R 16 91 H
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

MOT certificate, Missing, Replace



Service, Maintenance, Check



Door panel RR, Scratch(es), Acceptable



Backrest cover RL, Scratch(es), Acceptable



Bumper F, Scratch(es), Acceptable



Windscreen, Stone chip(s), Windscreen repair



Bonnet, Stone chip(s), Acceptable



Alloy rim FL, Scratch(es), Acceptable



Wing FL, Dent(s) and scratch(es), Repair and paint (complete)



Outside rear-view mirror cover L (upper), Scratch(es), Acceptable



Door FL, Scratch(es), Acceptable



Tyre repair kit, Missing, Check



Boot lid covering R, Scratch(es), Acceptable



Bumper R, Scratch(es), Paint



Tailgate / Boot, Scratch(es), Acceptable



Outer sill R, Scratch(es), Spot repair



Door FR, Scratch(es), Acceptable



Alloy rim RR, Scratch(es), Acceptable



Alloy rim FR, Scratch(es), Acceptable



Wing PR, Scratch(es), Polish

Wing RR, Surfaces, Polish



Bodywork, Not original part, Remove lettering



Roof, Chemical polution, Acceptable

