

INSPECTION REPORT

End Of Contract

GENERAL INFO

File	273989
License plate	CD7703
Vehicle identification number	WBA7W41060CD21560
Dossier	2019 177 028
Make	BMW 745Le 286 xDrive Aut
Mileage	81469.00
First registration	18/10/2019
	10/03/2025

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	3	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	









DAMAGES

Damages	Type	Acceptable
32	Front Bonnet // Painting	N
66	Wing Front Left // Polish	Y
133	Bumper Rear // Painting	N
193	Door Rear Right // Painting	N
214	Door Front Right // Repair & Painting	N
222	Side View Mirror Right // Painting	N
540	Interior // Repair 1	N



Damage Pictures





Door Rear Right // Painting-scratch



Bumper Rear // Painting-scratch




Front Bonnet // Painting-scratch



Wing Front Left // Polish-scratch



Side View Mirror Right // Painting-scratch



Door Front Right // Repair & Painting-scratch + dent



Interior // Repair 1-missing