



BMW 120 SAL PET AUT: MQ5001

Vinnnumber:	WBA81GE0007R63261	Versionname:	
First Registrationdate:	23/10/2024	Fiscalpower:	
Expertise Mileage:	27007	Power Kw:	
Bodytype:		Body colour	Grey
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:	Front		
Fueltype:	Petrol		
Maintenance	NOT OK		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	No		
Category	Passenger Car		
Registration Certificate Car (BE)	No		
Registration Certificate Home (BE)	No		

Options

Number of keys total	1	Luggage cover
Number keys remote	1	
Type of GPS	GPS big screen color	
Type of GPS storage	HD	

Tyres

	195/50/18/93 H			
Winter tyres:	Fr.L.	Goodyear: 7 mm	Fr.R.	Goodyear: 8 mm
	Re.L.	Vredestein: 7 mm	Re.R.	Vredestein: 7 mm
Tyre profile depth FL	7.0			
Tyre profile depth FR	8.0			
Tyre profile depth RL	7.0			
Tyre profile depth RR	7.0			
Tyre size FL	195/50 R 18 93 H			
Tyre size FR	195/50 R 18 93 H			
Tyre size RL	195/50 R 18 93 H			
Tyre size RR	195/50 R 18 93 H			
Tyre type FL	Winter			
Tyre type FR	Winter			
Tyre type RL	Winter			
Tyre type RR	Winter			
Tyre make FL	259			
Tyre make FR	259			
Tyre make RL	2480			
Tyre make RR	2480			

Assistance equipment

Repair kit	No	Compressor	No
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Service, Maintenance, Execute



Cigar lighter, Missing, Replace



Bumper grille, Broken, Replace



Bumper spoiler F, Dent(s), Spot repair




Bumper F, Scratch(es), Spot repair



Alloy rim RL, Scratch(es), Replace



Wing RL, Scratch(es), Polish



Alloy rim FL, Scratch(es), Repair and paint (complete)



Wing FL, Dent(s) and scratch(es), Repair and paint (complete)



Door FL, Dent(s), Paintless dent repair



Outside rear-view mirror housing L, Scratch(es), Repair and paint (complete)



Wheel lock adapter, Missing, Replace

No pictures to display

Tyre repair kit, Missing, Replace

No pictures to display

Compressor, Missing, Replace

No pictures to display

Bumper R, Scratch(es), Spot repair



Outside rear-view mirror housing R, Missing, Replace and paint



Alloy rim FR, Scratch(es), Repair and paint (complete)



Bodywork, Paint measurement, Acceptable

