



BMW 120 SAL PET AUT: WS8113

Vinnumber:	WBA81GE0507S15752	Versionname:	
First Registrationdate:	20/12/2024	Fiscalpower:	
Expertise Mileage:	32780	Power Kw:	115
Bodytype:		Body colour	Black
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:	Front		
Fueltype:	Petrol		
Maintenance	OK		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	No		
Category	Passenger Car		
Registration Certificate Car (BE)	No		
Registration Certificate Home (BE)	No		

Options

Number of keys total	1	Luggage cover
Number keys remote	1	
Type of GPS	GPS big screen color	
Type of GPS storage	HD	

Tyres

195/50/18/93 H				
Winter tyres:	Fr.L.	Vredestein: 4 mm	Fr.R.	Vredestein: 4 mm
	Re.L.	Vredestein: 6 mm	Re.R.	Vredestein: 6 mm
Tyre profile depth FL	4.0			
Tyre profile depth FR	4.0			
Tyre profile depth RL	6.0			
Tyre profile depth RR	6.0			
Tyre size FL	195/50 R 18 93 H			
Tyre size FR	195/50 R 18 93 H			
Tyre size RL	195/50 R 18 93 H			
Tyre size RR	195/50 R 18 93 H			
Tyre type FL	Winter			
Tyre type FR	Winter			
Tyre type RL	Winter			
Tyre type RR	Winter			
Tyre make FL	2480			
Tyre make FR	2480			
Tyre make RL	2480			
Tyre make RR	2480			

Assistance equipment

Spare wheel	No	Runflat	No
Emergency spare wheel	No		
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Floor covering, Worn, Replace



Interior, Not original part, Check



Interior, Not original part, Forfeit



Fire extinguisher, Missing, Replace



Bonnet, Stone chip(s), Touch up



Bumper F, Scratch(es), Repair and paint (complete)



Bumper moulding F, Scratch(es), Repair and paint (complete)



Alloy rim FL, Scratch(es), Repair and paint (complete)



Wing FL, Stone chip(s), Touch up



Door FL, Scratch(es), Polish



Door FL, Scratch(es), Touch up



Sill trim L, Scratch(es), Polish



Door RL, Scratch(es), Touch up



Spare wheel, Missing, Check



Boot lid covering R, Stain, Cleaning



Boot carpet, Stain, Cleaning



Bumper R, Scratch(es), Polish



Rear window, Scratch(es), Replace



Tyre FR, Deformed / Strained, Replace



Alloy rim FR, Scratch(es), Repair and paint (complete)



Step R, Scratch(es), Repair and paint (complete)



Door RR, Scratch(es), Touch up



Door RR, Scratch(es), Repair and paint (complete)



Wing RR, Scratch(es), Polish



Door FR, Scratch(es), Touch up



Outside rear-view mirror housing R, Scratch(es), Polish



Door FR, Dent(s), Paintless dent repair



Bodywork, Paint measurement, Acceptable



Roof, Scratch(es), Polish



Bodywork, Scratch(es), Polish

