



BMW 3er 330e iPerformance

VIN NO WBA8E11050K832122
Registration Number 050K832122



MOT Date

2026-10-01

Last Service



Number of Owners

2

Last Service Mileage



Number of Keys

2

First Registration Date

2017-10-13

Odometer Reading

113081 km

Country First Registered

Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20251010105526
Inspection Date / Place	2025-10-10 / BCA Oberndorf	Cosmetic Grade	2

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Plug - in Hybrid Electric Vehicle Petrol	Road Worthy	Yes
Colour	Blue	Engine Size (cc)	1998
Engine Size	2.0	No of Doors	4
Body Type	Sedan	Drive Train	Rear
Seat Colour		No of Seats	5
Seat Covering Name	Schwarz	Seat Covering	Cloth
Charging Cables	Occasional Use Charge	NEDC CO2 Rating (q/km)	44
Gearbox Type	Automatic		

Vehicle History & Documents

Service Book Available	Missing	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

Tinted Glass	Airbag Status	Ambientlighting	Bluetooth telephone interface
Enhanced speaker system	Front parking sensors	Remote central locking	CD Player
Leather steering wheel	Radio	USB Socket	Alloys wheels
Anti-lock braking	Cruise control	Front fog lamps	Remote adjusting wing mirrors
Stability control	Central locking	LED Headlamps	Rear parking sensors

Equipment Details


Air Conditioning	Three Zone Climate Control	Alloy Wheel Size	18
Enhanced Speaker System	harman/ kardon	Extra Wheel / Tyre Set	Winter Tyres - Alloy
Seat Heating	Front		

Wheels & Tyres

Extra Wheel - 1 Tyre Depth	5	Extra Wheel - 2 Tyre Depth	5
Extra Wheel - 3 Tyre Depth	5	Extra Wheel - 4 Tyre Depth	5
Right Front Tyre Depth	5	Left Front Tyre Depth	5
Right Rear Tyre Depth	5	Left Rear Tyre Depth	5

Cosmetic Damage

8 Schäden



0 Schäden



Component		Damage	Comments
1	Bumper / Front	Paint / Scratch / Scuff	
2	Rim / Back Left	Out of Bodywork / Scratch	
3	Tire / Back Right	Bodywork / Breakage / Crack	
4	Fender / Back Right	Bodywork / Dent / Dent	
5	Rim / Back Right	Paint / Stone Chip	
6	Rim / Front Right	Paint / Stone Chip	
7	Rim / Front Left	Paint / Stone Chip	
8	Fender / Front Right	Paint / Stone Chip	



1. Bumper / Front
Paint / Scratch / Scuff -



2. Rim / Back Left
Out of Bodywork / Scratch -



3. Tire / Back Right
Bodywork / Breakage / Crack -



4. Fender / Back Right
Bodywork / Dent / Dent -



5. Rim / Back Right
Paint / Stone Chip -



6. Rim / Front Right
Paint / Stone Chip -



7. Rim / Front Left
Paint / Stone Chip -



8. Fender / Front Right
Paint / Stone Chip -

Mechanical Condition

Equipments Test

Central Locking	✓	Electric Windows	✓
Audio Equipment	✓	AC / Heating System	✓
Main & Spare Keys Functioning	✓	Parking Sensors / Cameras Functioning	✓
Other Equipments	✓		

Control Lights

ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Airbag Warning Light	✓	Oil Pressure Warning Light	✓
Brake Warning Light	✓	Power Steering Warning Light	✓
Alternator / Battery	✓	No Dashboard Lights	✓
Display Defect	✓	Service Light	✓
Tire Pressure Monitoring System	✓		

Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

Gearbox

Gear Box	✓
----------	---

Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---

Hybrid/EV

Charge Lead Condition	✓	Charge Port Condition	✓
Hybrid System Fault	✓		

Test Drive Inspection

Steering Wheel

Steering | Noise / Anomaly

Engine

Engine Noise		The Gears Scratch / Skip / Abnormal Operation	
Fume Quantity		Power Loss	

Brake

Brake System Anomaly

General

Test Driven Status Not Performed

- No troubles detected, good condition or correct tests, according to vehicle age and mileage**
- Damages or malfunction detected that requires repairs by the buyer**
- Not applicable**
- Not tested**

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description. [User Guide](#)