

INSPECTION REPORT

End Of Contract

GENERAL INFO

File	285349
License plate	2BQA277
Vehicle identification number	WBA8E11060K419481
Dossier	2017 117 009
Make	BMW 330e iPerformance
Mileage	124681.00
First registration	01/08/2017
	17/06/2025

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
15	Bumper Front // Replace & Painting	N
133	Bumper Rear // Painting	N
161	Roof // Smart Repair Medium	Y
181	Wing Rear Right // Smart Repair Medium	N


Damage Pictures



Bumper Rear // Painting-scratch



Wing Rear Right // Smart Repair Medium-dent



Roof // Smart Repair Medium-dent



Bumper Front // Replace & Painting-cracked