

INSPECTION REPORT

End Of Contract

GENERAL INFO

File	268688
License plate	VW4957
Vehicle identification number	WBACV41050LZ86397
Dossier	2019176025
Make	BMW X5 25d xDrive 232 Aut
Mileage	136750.00
First registration	26/11/2019
	21/01/2025

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	N
67	Wing Front Left / Trim / Replace	N
103	Door Rear Left // Painting	N
225	Side View Mirror Right // Polish	Y
228	Side View Mirror Right / Direction Indicator / Replace	N

Damage Pictures



Side View Mirror Right // Polish-scratch



Side View Mirror Right / Direction Indicator / Replace-scratch



Door Rear Left // Painting-scratch



Wing Front Left / Trim / Replace-scratch



Bumper Front // Painting-scratch