



BMW 3er 325d DPF Cabrio Aut.

VIN NO WBADY51080E422457
Registration Number 080E422457



MOT Date

2026-10-01

Last Service

2016-04-22

Number of Owners

2

Last Service Mileage

50673

Number of Keys

2

First Registration Date

2011-01-31

Odometer Reading

93209 km

Country First Registered

Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20251009085309
Inspection Date / Place	2025-10-09 / ARS Altmann AG Wolnzach	Cosmetic Grade	4


Vehicle Summary




Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Diesel	Road Worthy	Yes
Colour	Black	Engine Size (cc)	2993
Engine Size	3.0	No of Doors	2
Body Type	Convertible	Drive Train	Rear
Seat Colour		No of Seats	4
Seat Covering Name		Seat Covering	Leather
Charging Cables		NEDC CO2 Rating (q/km)	168
Gearbox Type	Automatic		

Vehicle History & Documents

Service Book Available	Present	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warranty			







Equipment

Airbag Status	Anti-lock braking	Cruise control	Front fog lamps
Remote adjusting wing mirrors	Satellite navigation	CD Player	Electrically adjustable seats
Leather steering wheel	Rear parking sensors	Alloys wheels	Bi Xenon Headlamps
Diesel particulate filter	Front parking sensors	Remote central locking	Stability control
Central locking	Electrically folding wing mirrors	Radio	

Equipment Details


Air Conditioning	Dual Zone Climate Control	Alloy Wheel Size	17
Extra Wheel / Tyre Set	Summer Tyres - Alloy	Seat Heating	Front

Wheels & Tyres


Extra Wheel - 1 Tyre Depth	4	Extra Wheel - 2 Tyre Depth	4
Extra Wheel - 3 Tyre Depth	4	Extra Wheel - 4 Tyre Depth	4
Right Front Tyre Depth	4	Left Front Tyre Depth	4
Right Rear Tyre Depth	4	Left Rear Tyre Depth	4

Cosmetic Damage

11 Schäden




0 Schäden



Component		Damage	Comments
1	Tailgate	Paint / Scratch / Scuff	
2	Bumper / Back	Paint / Scratch / Scuff	
3	Rim / Back Left	Out of Bodywork / Scratch	
4	Rim / Front Right	Out of Bodywork / Scratch	
5	Bumper / Front	Paint / Scratch / Scuff	
6	Mirror Shell / Front Right	Paint / Scratch / Scuff	
7	Bumper / Back	Paint / Scratch / Scuff	
8	Rocker Panel / Center Left	Paint / Scratch / Scuff	
9	Bumper / Front	Paint / Scratch / Scuff	
10	Side Panel / Back Left	Paint / Scratch / Scuff	
11	Door / Front Left	Paint / Scratch / Scuff	



1. Tailgate
Paint / Scratch / Scuff -




2. Bumper / Back
Paint / Scratch / Scuff -



3. Rim / Back Left
Out of Bodywork / Scratch -



4. Rim / Front Right
Out of Bodywork / Scratch -




5. Bumper / Front
Paint / Scratch / Scuff -




6. Mirror Shell / Front Right
Paint / Scratch / Scuff -



7. Bumper / Back
Paint / Scratch / Scuff -



8. Rocker Panel / Center Left
Paint / Scratch / Scuff -



9. Bumper / Front
Paint / Scratch / Scuff -



10. Side Panel / Back Left
Paint / Scratch / Scuff -



11. Door / Front Left
Paint / Scratch / Scuff -

Mechanical Condition

Control Lights

ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Diesel Particulate Filter Light	✓	Airbag Warning Light	✓
Oil Pressure Warning Light	✓	Brake Warning Light	✓
Power Steering Warning Light	✓	Alternator / Battery	✓
No Dashboard Lights	✓	Display Defect	✓
Service Light	✓	Tire Pressure Monitoring System	✓

Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

Gearbox

Gear Box	✓
----------	---

Equipments Test

Central Locking	✓	Main & Spare Keys Functioning	✓
Electric Windows	✓	Navigation System	✓
Audio Equipment	✓	Parking Sensors / Cameras Functioning	✓
AC / Heating System	✓		

Levels

Brakes Fluid	NA	Coolant Fluid	NA
--------------	----	---------------	----

Test Drive Inspection

Engine			
Fume Quantity	✓	Engine Noise	✓
The Gears Scratch / Skip / Abnormal Operation	✓	Power Loss	✓
Brake			
Brake System Anomaly	✓		
Steering Wheel			
Steering Noise / Anomaly	✓		
General			
Test Driven Status	✓		
✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage			
! Damages or malfunction detected that requires repairs by the buyer			
NA Not applicable			
☐ Not tested			

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)