

INSPECTION REPORT

End Of Contract


GENERAL INFO

File	285829
License plate	1XMS235
Vehicle identification number	WBAJA91030CE18233
Dossier	2019 324 141
Make	BMW 530e 170kW
Mileage	21518.00
First registration	13/02/2020
	18/06/2025

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	





DAMAGES		
Damages	Type	Acceptable
611	Front Left Door Interior Coating // Repair	N

Damage Pictures



Front Left Door Interior Coating // Repair-Incinerated