

INSPECTION REPORT

End Of Contract

GENERAL INFO

File	290695
License plate	1WGC197
Vehicle identification number	WBAJH110205N45277
Dossier	2019 036 016
Make	BMW X1 sDrive 16d 85kW
Mileage	180527
First registration	27/05/2019
client availability date	04/08/2025
inspectionDate	08/08/2025

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		Y	





DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	N
35	Front Bonnet // Polish	Y
83	Door Front Left // Painting	N
117	Wing Rear Left / Trim / Replace	Y
124	Light / Rear left / Replace	Y
154	Rear Bonnet // Repair & Painting	N
174	Light / Rear Right / Replace	Y
181	Wing Rear Right // Smart Repair Medium	Y
186	Wing Rear Right // Polish	Y
196	Door Rear Right // Polish	Y
214	Door Front Right // Repair & Painting	Y
222	Side View Mirror Right // Painting	Y
236	Wing Front right // Polish	Y
237	Wing Front right / Trim / Replace	Y
539	Trunk Compartment / Back Coating / Replace	Y
540	Interior // Repair 1	N
568	Dashboard / Ventilation Outlet / Replace	N
860	Interior Cleaning // Small	N


Damage Pictures



Bumper Front // Painting-scratch





Wing Front right / Trim / Replace-scratch



Wing Front right // Polish-scratch



Side View Mirror Right // Painting-scratch



Door Rear Right // Polish-scratch



Wing Rear Right // Polish-scratch



Wing Rear Right // Smart Repair Medium-scratch



Trunk Compartment / Back Coating / Replace-scratch



Light / Rear Right / Replace-scratch



Light / Rear left / Replace-scratch



Wing Rear Left / Trim / Replace-scratch




Interior // Repair 1-scratch



Door Front Left // Painting-scratch



Rear Bonnet // Repair & Painting-scratch + dent



Door Front Right // Repair & Painting-scratch + dent



Dashboard / Ventilation Outlet / Replace-cracked



Front Bonnet // Polish-Chemical reaction

