



BMW 5-Reeks (MKL): 1VUD798

Vinnumber:	WBAJP11060BJ26711	Versionname:	518d Touring (G31) 2.0d 136pk/cv 5p Aut.
First Registrationdate:	1/03/2019	Fiscalpower:	
Expertise Mileage:	109508	Power Kw:	100
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:			
Maintenance	OK		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	No Tow bar
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

	225/55/17/97 Y			
Summer tyres:	Fr.L.	Dunlop: 4 mm	Fr.R.	Dunlop: 4 mm
	Re.L.	Dunlop: 5 mm	Re.R.	Dunlop: 5 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				225/55 R 17 97 Y
Tyre size FR				225/55 R 17 97 Y
Tyre size RL				225/55 R 17 97 Y
Tyre size RR				225/56 R 17 97 Y
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				257
Tyre make FR				257
Tyre make RL				257
Tyre make RR				257

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Roof liner, Stain, Cleaning



Bumper F, Scratch(es), Repair and paint (complete)




Windscreen, Stone chip(s), Windscreen repair



Door FL, Scratch(es), Acceptable



Wing RL, Repaired, Check



Wing FL, Repaired, Check



Tailgate / Boot, Scratch(es), Acceptable



Bumper R, Scratch(es), Acceptable



Step R, Scratch(es), Acceptable



Wing RR, Scratch(es), Repair and paint (complete)



Door RR, Scratch(es), Repair and paint (complete)



Door FR, Scratch(es), Acceptable



Sill trim R, Scratch(es), Repair and paint (complete)



Outside rear-view mirror housing R, Scratch(es), Acceptable



Alloy rim FR, Scratch(es), Acceptable



Bodywork, Paint measurement, Acceptable

