

# INSPECTION REPORT




**End Of Contract**

## GENERAL INFO

|                               |                             |
|-------------------------------|-----------------------------|
| File                          | 290112                      |
| License plate                 | 2EGF550                     |
| Vehicle identification number | WBAJP11070BJ26751           |
| Dossier                       | 2019 051 086                |
| Make                          | BMW 518d touring 110kW Aut. |
| Mileage                       | 136051                      |
| First registration            | 26/06/2019                  |
| client availability date      | 07/06/2025                  |
| inspectionDate                | 04/08/2025                  |

## CHECK POINTS

| Description               | Number | Present | Remark |
|---------------------------|--------|---------|--------|
| Original license plate    |        | Y       |        |
| Registration Part 2       |        | N       |        |
| Keys                      | 2      | Y       |        |
| Spare wheel               |        | N       |        |
| Towbar (+keys)            |        | Y       |        |
| Certificate of conformity |        | Y       |        |
| Registration certificate  |        | Y       |        |
| Repair kit                |        | Y       |        |
| RunOnFlat                 |        | N       |        |
| Charging cable            |        | N       |        |
| Charge back wrong tyres   |        | N       |        |





## DAMAGES

| Damages | Type                                | Acceptable |
|---------|-------------------------------------|------------|
| 12      | Bumper Front // Smart Repair Large  | N          |
| 41      | Windshield // Replace               | N          |
| 75      | Side View Mirror Left // Polish     | Y          |
| 83      | Door Front Left // Painting         | N          |
| 116     | Wing Rear Left // Polish            | Y          |
| 134     | Bumper Rear // Repair & Painting    | N          |
| 151     | Rear Bonnet // Smart Repair Medium  | N          |
| 159     | Rear Bonnet / Rear Window / Replace | Y          |
| 186     | Wing Rear Right // Polish           | Y          |
| 225     | Side View Mirror Right // Polish    | Y          |
| 840     | Interior Cleaning // Large          | N          |


## Damage Pictures



Side View Mirror Right // Polish-scratch





Wing Rear Right // Polish-scratch





Rear Bonnet // Smart Repair Medium-scratch




Rear Bonnet / Rear Window / Replace-scratch



Wing Rear Left // Polish-scratch




Side View Mirror Left // Polish-scratch




Bumper Front // Smart Repair Large-scratch



Bumper Rear // Repair & Painting-scratch + dent



Windshield // Replace-cracked



Door Front Left // Painting-Chemical reaction



Interior Cleaning // Large-stain