

INSPECTION REPORT

End Of Contract

GENERAL INFO

File	288728
License plate	1VHM063
Vehicle identification number	WBAJP310X0BT72656
Dossier	2018 165 096
Make	BMW 520d touring 120kW Aut.
Mileage	166897
First registration	15/11/2018
client availability date	10/07/2025
inspectionDate	24/07/2025

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		Y	






DAMAGES

Damages	Type	Acceptable
11	Bumper Front // Smart Repair Medium	N
81	Door Front Left // Smart Repair Medium	Y
104	Door Rear Left // Repair & Painting	Y
114	Wing Rear Left // Repair & Painting	Y
211	Door Front Right // Smart Repair Medium	Y


Damage Pictures



Bumper Front // Smart Repair Medium-scratch



Door Front Right // Smart Repair Medium-scratch



Door Front Left // Smart Repair Medium-scratch



Wing Rear Left // Repair & Painting-scratch + dent



Door Rear Left // Repair & Painting-scratch + dent