DEKRA

DEKRA Automotive Solutions

Appraisal Report

Vehicle details

VIN	WBAJU8105 P9P36456	Brand	BMW	Maintenance date	14/06/2024
Licence Plate	LOO763	Model	X5-G05-2018	Maintenance mileage	23 547 km
Registration date	20/01/2023	Year	2023	Exterior Color	Other
Odometer	45 968 km	Engine size	-	interior Color	
Fuel	Diesel	Body Type	SUV CrossOver	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	8		

Inspection Details

Inspection date	06/10/2025	Inspection loc.	Eurotransport Kungsängen		



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
Rain and light sensor	✓
Leather	✓
GPS system	✓
Bluetooth	✓
Front radars	✓
Alloy wheel rims	✓
Reversing radars	✓
Reversing camera	✓
Automatic Gearbox	✓
Electric seats	✓
Metallic paint	✓
Central locking	✓
4x4	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓
Lane Keeping Assist (LKA)	✓
Adaptive Cruise Control (ACC)	✓
Led lighting	✓

Removable element

Load cover	✓
Refill emergency kit	✗

Technical Document

Service manual holder	✓
User manual	✓
Spare key	✓
Key	✓
Remote key	✓

Tyres

Nokian 255/55/18 W Summer 7.0 mm

Nokian 255/55/18 W Summer 7.0 mm



Nokian 255/55/18 W Summer 7.0 mm

Nokian 255/55/18 W Summer 7.0 mm

Winter kit

Nokian 265/50/19 R Winter 8.0 mm

Nokian 265/50/19 R Winter 8.0 mm



Nokian 265/50/19 R Winter 8.0 mm

Nokian 265/50/19 R Winter 8.0 mm

Damages

1

Part	Refill emergency kit
Position	-
Damages	Missing
Severity	-
Repair mode	Lumpsum replacement

2

Part	Bumper
Position	Front
Damages	Scratched
Severity	-
Repair mode	Polishing

3

Part	Door
Position	Front right
Damages	Scratched
Severity	-
Repair mode	For info

4

Part	Door sill
Position	Front right
Damages	Scratched
Severity	-
Repair mode	For info

5

Part	Door
Position	Back right
Damages	Stained/dirty
Severity	-
Repair mode	For info

6

Part	Door sill
Position	Back right
Damages	Scratched
Severity	-
Repair mode	For info

7

Part	Wing
Position	Back right
Damages	Scratched
Severity	-
Repair mode	For info

8

Part	Tailgate / Boot door
Position	Back
Damages	Scratched
Severity	-
Repair mode	Polishing

9

Part	Bumper
Position	Back
Damages	Scratched
Severity	-
Repair mode	For info

10

Part	Wing
Position	Back left
Damages	Dented
Severity	-
Repair mode	For info

11

Part	Door sill
Position	Back left
Damages	Scratched
Severity	-
Repair mode	Lumsum Paintworks

12

Part	Door
Position	Back left
Damages	Dented
Severity	-
Repair mode	For info

13

Part	Wheel arch trim
Position	Back left
Damages	Scratched
Severity	-
Repair mode	For info

14

Part	Door
Position	Front left
Damages	Dented
Severity	-
Repair mode	For info

15

Part	Other technic
Position	-
Damages	Defective
Severity	-
Repair mode	For info

Front sensor cover damage, not abel to see sensor if damage