

VIN	WBAJU8105 P9P36456
Licence Plate	LOO763
Registration date	20/01/2023
Odometer	45 968 km
Fuel	Diesel
Seats	-
Doors	5

Brand	BMW
Model	X5-G05-2018
Year	2023
Engine size	-
Body Type	SUV CrossOver
Transmission	Automatic
Gears	8

Maintenance date	14/06/2024
Maintenance mileage	23 547 km
Exterior Color	Other
interior Color	
Next technical inspection	-
CO2	-

Inspection date 06/10/2025

Inspection loc. Eurotransport Kungsängen

Automated air-conditioning	✔
Cruise control	✔
Rain and light sensor	✔
Leather	✔
GPS system	✔
Bluetooth	✔
Front radars	✔
Alloy wheel rims	✔
Reversing radars	✔
Reversing camera	✔
Automatic Gearbox	✔
Electric seats	✔
Metallic paint	✔
Central locking	✔
4x4	✔
Side rails	✔
Park Distance Control	✔
Audio System	✔
Lane Keeping Assist (LKA)	✔
Adaptive Cruise Control (ACC)	✔
Led lighting	✔


Load cover	
Refill emergency kit	

Service manual holder	
User manual	
Spare key	
Key	
Remote key	

DEKRA Automotive Solutions

Tyres

Nokian 255/55/18 W Summer 7.0 mm



Nokian 255/55/18 W Summer 7.0 mm




Nokian 255/55/18 W Summer 7.0 mm



Nokian 255/55/18 W Summer 7.0 mm

Winter kit

Nokian 265/50/19 R Winter 8.0 mm



Nokian 265/50/19 R Winter 8.0 mm



Nokian 265/50/19 R Winter 8.0 mm



Nokian 265/50/19 R Winter 8.0 mm

Damages

1



Part	Refill emergency kit
Position	-
Damages	Missing
Severity	-
Repair mode	Lumpsum replacement

2



Part	Bumper
Position	Front
Damages	Scratched
Severity	-
Repair mode	Polishing

3



Part	Door
Position	Front right
Damages	Scratched
Severity	-
Repair mode	For info

4



Part	Door sill
Position	Front right
Damages	Scratched
Severity	-
Repair mode	For info

5



Part	Door
Position	Back right
Damages	Stained/dirty
Severity	-
Repair mode	For info

6



Part	Door sill
Position	Back right
Damages	Scratched
Severity	-
Repair mode	For info

7



Part	Wing
Position	Back right
Damages	Scratched
Severity	-
Repair mode	For info

8



Part	Tailgate / Boot door
Position	Back
Damages	Scratched
Severity	-
Repair mode	Polishing

9



Part	Bumper
Position	Back
Damages	Scratched
Severity	-
Repair mode	For info

10



Part	Wing
Position	Back left
Damages	Dented
Severity	-
Repair mode	For info

DEKRA Automotive Solutions

11



Part

Door sill

Position

Back left

Damages

Scratched

Severity

-

Repair mode

Lumsum Paintworks

●

●

12



Part

Door

Position

Back left

Damages

Dented

Severity

-

Repair mode

For info

●

●

13



Part

Wheel arch trim

Position

Back left

Damages

Scratched

Severity

-

Repair mode

For info

●

●

14



Part

Door

Position

Front left

Damages

Dented

Severity

-

Repair mode

For info

●

●

●

●

15



Part

Other technic

Position

-

Damages

Defective

Severity

-

Repair mode

For info

Front sensor cover damage, not able to see sensor if damage

●

●