



VOLVO XC90: AB0470			
Vinnnumber:	WBAJU810609F70702	Versionname:	2.0 D5 4WD GEARTRONIC R-DESIGN 5PL.
First Registrationdate:	15/03/2021	Fiscalpower:	
Expertise Mileage:	128925	Power Kw:	210
Bodytype:		Body colour:	Black
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:	Front	Parking lot:	3326
Fueltype:	Hybrid Diesel		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Registration Certificate Home (BE):	No		

Options			
Number of keys total:	2	Seats electric F L	
Cruise Control		Seats electric F R	
Steering wheel multifunctional		Sun Roof electric	
Seats F heated		Panoramic roof	
Radio multimedia		Luggage cover	
Type of headlighting	Headlighting LED	Front parking sensors	
Type of GPS	GPS big screen color	Rear parking sensors	
Type of Lining	Lining leather	Type of Tow bar	No Tow bar
Type of climate control	Autom climate control		
Sport seats			

Limited Technical Inspection

Degree of wear

275/35/22/103 Y			
Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R. Continental: 3 mm
	Re.L.	Continental: 5 mm	Re.R. Continental: 3 mm
Tyre profile depth FL			4.0
Tyre profile depth FR			3.0
Tyre profile depth RL			5.0
Tyre profile depth RR			3.0
Tyre size FL			275/35 R 22 103 Y
Tyre size FR			275/35 R 22 104 Y
Tyre size RL			315/30 R 22 107 Y
Tyre size RR			315/30 R 22 107 Y
Tyre type FL			Summer
Tyre type FR			Summer
Tyre type RL			Summer
Tyre type RR			Summer
Tyre make FL			256
Tyre make FR			256
Tyre make RL			256
Tyre make RR			256

Assistance equipment

Number of charging cables (normal)	0	
Number of charging cables (rapid charge)	0	
Total cost ex VAT		398,08
Interior, Damaged, Acceptable		0,00



Wing FL, Scratch(es), Polish

0,00



Door FL, Scratch(es), Acceptable

0,00



Door RL, Scratch(es), Acceptable

0,00



Tailgate / Boot, Scratch(es), Acceptable

0,00



Alloy rim FR polished, Scratch(es), Repair and paint (complete)

199,04



Wing trim FR, Scratch(es), Acceptable

0,00



Door FR, Scratch(es), Acceptable

0,00



Alloy rim RR polished, Scratch(es), Repair and paint (complete)

199,04

