



BMW 6 Reeks Gran Turismo: 1YDE819			
Vinnnumber:	WBAJX21070CE88002	Versionname:	6 Reeks Gran Turismo 620d (120kW) 120kW/163pk 5D/P Auto-8
First Registrationdate:	24/07/2020	Fiscalpower:	
Expertise Mileage:	185655	Power Kw:	120
Bodytype:		Body colour	Dark Blue
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:	Back	Parking lot	b518
Fueltype:	Diesel		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Bodywork	Clean		
Interior	Clean		

Options			
Number of keys total	2	Radio	
Number keys remote	2	Lining leather	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Navigation with screen			
Airco electronic			
Rims alloy			

Limited Technical Inspection			
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Transmission	OK

Degree of wear				
	275/40/19/105 V			
Winter tyres:	Fr.L.	Pirelli: 4 mm	Fr.R.	Pirelli: 4 mm
	Re.L.	Pirelli: 4 mm	Re.R.	Pirelli: 4 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				275/40 R 19 105 V
Tyre size FR				275/40 R 19 105 V
Tyre size RL				275/40 R 19 105 V
Tyre size RR				275/40 R 19 105 V
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				264
Tyre make FR				264
Tyre make RL				264
Tyre make RR				264

Assistance equipment			
Number of charging cables (normal)	0	Compressor	No
Number of charging cables (rapid charge)	0		

Backrest cover FL, Scratch(es), Smart repair



Backrest cover FR, Scratch(es), Smart repair



Door panel RL, Tear, Smart repair



Door panel RR, Tear, Smart repair



Interior, Dirty, Cleaning



Bumper F, Scratch(es), Repair and paint (complete)



Windscreen, Stone chip(s), Windscreen repair



Alloy rim RL, Scratch(es), Repair and paint (complete)




Wing RL, Bad repair, Check



Step L, Dent(s) and scratch(es), Spot repair




Door RL, Bad repair, Check



Outside rear-view mirror housing L, Scratch(es), Acceptable




Door FL, Bad repair, Check




Outer sill L, Deformed / Strained, Replace and paint






Wing FL, Scratch(es), Acceptable



Alloy rim FL, Scratch(es), Repair and paint (complete)




Compressor, Missing, Replace



Boot lid covering R, Scratch(es), Replace




Interior covering C pillar L, Scratch(es), Smart repair




Interior covering C pillar R, Scratch(es), Acceptable



Tailgate / Boot, Dent(s), Spot repair



Bumper R, Dent(s) and scratch(es), Repair and paint (complete)



Bumper moulding R, Scratch(es), Spot repair



Alloy rim FR, Scratch(es), Repair and paint (complete)



Outside rear-view mirror housing R, Scratch(es), Polish




Outside rear-view mirror base R, Scratch(es), Polish





Outer sill R, Scratch(es), Polish




Door RR, Dent(s) and scratch(es), Repair and paint (complete)



Door FR, Dent(s) and scratch(es), Acceptable



Wing RR, Dent(s), Spot repair



Alloy rim RR, Scratch(es), Repair and paint (complete)



Roof, Dent(s), Paintless dent repair

