



BMW X5: 1YFZ545			
Vinnumber:	WBATA610109D39194	Versionname:	xDrive45e (155kW)
First Registrationdate:	19/08/2020	Fiscalpower:	
Expertise Mileage:	187617	Power Kw:	155
Bodytype:		Body colour	Grey
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:		Parking lot	1yfz545
Fueltype:	Hybrid Petrol		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Registration Certificate Home (BE)	No		
Options			
Number of keys total	2	Seats electric F L	
Cruise Control		Seats electric F R	
Steering wheel multifunctional		Luggage cover	
Seats F heated		Front parking sensors	
Radio multimedia		Rear parking sensors	
Type of headlighting	Headlighting LED	Type of Tow bar	No Tow bar
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		
Sport seats			
Limited Technical Inspection			
Tyres			
Summer tyres:	265/50/19/110 Y		
	Fr.L.	Vredestein: 3 mm	Fr.R.
	Re.L.	Vredestein: 2 mm	Re.R.
			Vredestein: 2 mm
Tyre profile depth FL			3.0
Tyre profile depth FR			3.0
Tyre profile depth RL			2.0
Tyre profile depth RR			2.0
Tyre size FL			265/50 R 19 110 Y
Tyre size FR			265/50 R 19 110 Y
Tyre size RL			265/50 R 19 110 Y
Tyre size RR			265/50 R 19 110 Y
Tyre type FL			Summer
Tyre type FR			Summer
Tyre type RL			Summer
Tyre type RR			Summer
Tyre make FL			2480
Tyre make FR			2480
Tyre make RL			2480
Tyre make RR			2480
Assistance equipment			
Number of charging cables (normal)	1		
Number of charging cables (rapid charge)	1		
Total cost ex VAT			0,00
Interior, Worn, Acceptable			0,00



Roof liner, Dirty, Cleaning	0,00
-----------------------------	------



Bumper F, Scratch(es), Repair and paint (complete)	0,00
--	------




Alloy rim FL, Scratch(es), Repair and paint (complete)	0,00
--	------



Tyre FL, Tear, Acceptable	0,00
---------------------------	------




Door FL, Dent(s), Paintless dent repair	0,00
---	------



Door FL, Scratch(es), Polish 0,00



Wing trim FL, Scratch(es), Replace 0,00



Tailgate / Boot, Bad repair, Repair and paint (complete) 0,00



Rear light R, Scratch(es), Polish 0,00



Alloy rim FR, Scratch(es), Repair and paint (complete) 0,00



Wing trim FR, Scratch(es), Replace 0,00



Tyre FR, Tear, Acceptable 0,00



Wing FR, Scratch(es), Acceptable		0,00
		
A-pillar right, Scratch(es), Acceptable		0,00
		
Alloy rim RR, Scratch(es), Repair and paint (complete)		0,00
		
Wing RR, Chemical polution, Polish		0,00
		
Roof, Chemical polution, Repair and paint (complete)		0,00
		