

Vehicle details

VIN	WBATA6106 09D38834	Brand	BMW	Maintenance date	-
Licence Plate	K1-78-JG	Model	X5 xDrive45e 5d	Maintenance mileage	-
Registration date	08/01/2021	Year	2021	Exterior Color	White Solid
Odometer	192 635 km	Engine size	2998	interior Color	Black
Fuel	Hybrid petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	14/01/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
Leather	✓
GPS system	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Heating seats	✓
Electric seats	✓
Tow	✓
Central locking	✓
Electric windows	✓
4x4	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓


Removable element

Wireless charger	✗
Load cover	✓
Vehicle charger	✓

Technical Document

User manual	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres





Hankook 265/50/19 Summer 7.0 mm

Hankook 265/50/19 Summer 7.0 mm


Hankook 265/50/19 Summer 6.0 mm

Hankook 265/50/19 Summer 6.0 mm



Exterior

3		<table border="0"> <tr><td>Part</td><td>Door</td></tr> <tr><td>Position</td><td>Back right</td></tr> <tr><td>Damages</td><td>Improper repair</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Repair</td></tr> </table>	Part	Door	Position	Back right	Damages	Improper repair	Severity	-	Repair mode	Repair	4		<table border="0"> <tr><td>Part</td><td>Door</td></tr> <tr><td>Position</td><td>Front right</td></tr> <tr><td>Damages</td><td>Improper repair</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Repair</td></tr> </table>	Part	Door	Position	Front right	Damages	Improper repair	Severity	-	Repair mode	Repair
Part	Door																								
Position	Back right																								
Damages	Improper repair																								
Severity	-																								
Repair mode	Repair																								
Part	Door																								
Position	Front right																								
Damages	Improper repair																								
Severity	-																								
Repair mode	Repair																								

Interior damage

2		<table border="0"> <tr><td>Part</td><td>Interior cleaning</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Stained/dirty</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Cleaning</td></tr> </table>	Part	Interior cleaning	Position	-	Damages	Stained/dirty	Severity	-	Repair mode	Cleaning
Part	Interior cleaning											
Position	-											
Damages	Stained/dirty											
Severity	-											
Repair mode	Cleaning											

Others

1		<table border="0"> <tr><td>Part</td><td>Wireless charger</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Missing</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>For info</td></tr> </table>	Part	Wireless charger	Position	-	Damages	Missing	Severity	-	Repair mode	For info
Part	Wireless charger											
Position	-											
Damages	Missing											
Severity	-											
Repair mode	For info											
5		<table border="0"> <tr><td>Part</td><td>Damage appraisal</td></tr> <tr><td>Position</td><td>Front</td></tr> <tr><td>Damages</td><td>Stone impact</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>For info</td></tr> </table>	Part	Damage appraisal	Position	Front	Damages	Stone impact	Severity	-	Repair mode	For info
Part	Damage appraisal											
Position	Front											
Damages	Stone impact											
Severity	-											
Repair mode	For info											