

**BMW X5: 1YKB814**

Vinnumber:	WBATA610609D74751	Versionname:	xDrive45e (155kW)
First Registrationdate:	17/09/2020	Fiscalpower:	
Expertise Mileage:	86045	Power Kw:	155
Bodytype:		Body colour:	Blue
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	2410
Fueltype:	Hybrid Petrol		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Registration Certificate Home (BE):	No		

Options

Number of keys total	2	Seats electric F L	
Cruise Control		Seats electric F R	
Steering wheel multifunctional		Luggage cover	
Seats F heated		Front parking sensors	
Radio multimedia		Rear parking sensors	
Type of headlighting	Headlighting LED	Type of Tow bar	No Tow bar
Type of GPS	GPS big screen color		
Type of Lining	Lining artificial leather		
Type of climate control	Autom climate control		
Head-up Display			

Limited Technical Inspection**Tyres**

	275/45/20/110 Y			
Summer tyres:	Fr.L.	Pirelli: 4 mm	Fr.R.	Pirelli: 4 mm
	Re.L.	Pirelli: 4 mm	Re.R.	Pirelli: 4 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				275/45 R 20 110 Y
Tyre size FR				275/45 R 20 110 Y
Tyre size RL				305/40 R 20 110 Y
Tyre size RR				305/40 R 20 110 Y
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				264
Tyre make FR				264
Tyre make RL				264
Tyre make RR				264

Assistance equipment

Number of charging cables (normal)	1	Runflat	Yes
Number of charging cables (rapid charge)	1		

Total cost ex VAT	0,00
Bumper F, Scratch(es), Acceptable	0,00



Bonnet, Scratch(es), Acceptable 0,00



Bumper grille, Scratch(es), Acceptable 0,00



Alloy rim FL polished, Scratch(es), Repair and paint (complete) 0,00



Wing FL, Scratch(es), Acceptable 0,00




Alloy rim RL polished, Scratch(es), Repair and paint (complete) 0,00



Door RL, Scratch(es), Acceptable 0,00



Wing RL, Scratch(es), Acceptable 0,00



Outside rear-view mirror housing L, Scratch(es), Acceptable 0,00



Bumper R, Scratch(es), Acceptable 0,00



Tailgate / Boot, Scratch(es), Acceptable 0,00



Alloy rim FR polished, Scratch(es), Repair and paint (complete) 0,00



Sill trim R, Scratch(es), Acceptable 0,00



Door RR, Scratch(es), Acceptable 0,00



Alloy rim RR polished, Scratch(es), Repair and paint (complete) 0,00



Wing RR, Scratch(es), Acceptable 0,00



Roof, Scratch(es), Acceptable 0,00

