

INSPECTION REPORT

End Of Contract

GENERAL INFO

File	291637
License plate	2AUC935
Vehicle identification number	WBATA610609G90666
Dossier	2021027164
Make	BMW X5 xDrive 45e 155kW
Mileage	81907
First registration	19/07/2021
client availability date	18/08/2025
inspectionDate	28/08/2025

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		Y	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
133	Bumper Rear // Painting	N
138	Bumper Rear / Lower Cover Not Painted / Replace	N
139	Bumper Rear / Spoiler / Replace	N
148	Back Side / Reflector R / Replace	N
153	Rear Bonnet // Painting	N
174	Light / Rear Right / Replace	N
175	Light / Rear Right On Rear Bonnet / Replace	N
187	Wing Rear Right / Trim / Replace	N
222	Side View Mirror Right // Painting	N
227	Side View Mirror Right / Shell / Replace Not Painted	N
228	Side View Mirror Right / Direction Indicator / Replace	N
13	Bumper Front // Painting	Y
18	Bumper Front / Spoiler / Replace	Y
63	Wing Front Left // Painting	Y
83	Door Front Left // Painting	Y
91	Rocker Panel Left // Smart Repair Medium	Y
116	Wing Rear Left // Polish	Y
183	Wing Rear Right // Painting	Y
193	Door Rear Right // Painting	Y
214	Door Front Right // Repair & Painting	N
310	Wheel Two Tone Front Left // Repair	N
320	Wheel Two Tone Rear Left // Repair	N
330	Wheel Two Tone Rear Right // Repair	N
340	Wheel Two Tone Front Right // Repair	N
684	Charger Cable //	N

Damage Pictures



Wing Rear Left // Polish-scratch



Door Front Left // Painting-scratch



Wing Front Left // Painting-scratch



Wheel Two Tone Front Left // Repair-scratch



Bumper Front / Spoiler / Replace-scratch



Bumper Front // Painting-scratch



Wheel Two Tone Rear Left // Repair-scratch



Wheel Two Tone Front Right // Repair-scratch



Wheel Two Tone Rear Right // Repair-scratch



Door Rear Right // Painting-scratch



Wing Rear Right // Painting-scratch



Door Front Right // Repair & Painting-scratch + dent



Rocker Panel Left // Smart Repair Medium-scratch + dent



Charger Cable //-missing



Light / Rear Right / Replace-cracked



Wing Rear Right / Trim / Replace-scratch





Bumper Rear // Painting-scratch



Bumper Rear / Spoiler / Replace-scratch




Bumper Rear / Lower Cover Not Painted / Replace-scratch




Back Side / Reflector R / Replace-scratch



Rear Bonnet // Painting-scratch



Light / Rear Right On Rear Bonnet / Replace-scratch



Side View Mirror Right / Shell / Replace Not Painted-scratch



Side View Mirror Right // Painting-scratch



Side View Mirror Right / Direction Indicator / Replace-cracked