

INSPECTION REPORT


End Of Contract

GENERAL INFO

File	289865
License plate	RS5530
Vehicle identification number	WBATA610709H12271
Dossier	2021 028 014
Make	BMW X5 45e xDrive 286 PHEV SP-
Mileage	142092
First registration	13/07/2021
client availability date	24/07/2025
inspectionDate	25/07/2025

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		N	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
32	Front Bonnet // Painting	N
71	Side View Mirror Left // Plastic Repair	N
104	Door Rear Left // Repair & Painting	Y
136	Bumper Rear // Polish	Y
139	Bumper Rear / Spoiler / Replace	N
152	Rear Bonnet // Smart Repair Large	N
159	Rear Bonnet / Rear Window / Replace	N
196	Door Rear Right // Polish	Y
214	Door Front Right // Repair & Painting	N
236	Wing Front right // Polish	Y

Damage Pictures




Door Rear Right // Polish-scratch



Rear Bonnet / Rear Window / Replace-scratch



Rear Bonnet // Smart Repair Large-scratch



Bumper Rear // Polish-scratch



Side View Mirror Left // Plastic Repair-scratch




Wing Front right // Polish-scratch




Bumper Rear / Spoiler / Replace-dent



Door Rear Left // Repair & Painting-scratch + dent



Door Front Right // Repair & Painting-scratch + dent



Front Bonnet // Painting-scratch + dent