



## BMW X5 X5 xDrive45e

VIN NO WBATA610809F15237  
Registration Number 0809F15237



MOT Date



Last Service

2024-01-04

Number of Owners



Last Service Mileage

73403

Number of Keys



First Registration Date

2021-01-13

Odometer Reading



99299 km

Country First Registered



Germany

### Inspection Report Summary

Customer	BCA Online	Report Number	P20250922101709
Inspection Date / Place	2025-09-22 / BCA Oberndorf	Cosmetic Grade	3

### Vehicle Summary


Vehicle Condition	Runner	VAT Type	Qualifying
Fuel Type	Plug - in Hybrid Electric Vehicle Petrol	Road Worthy	Yes
Colour	Grey	Engine Size (cc)	2998
Engine Size	3.0	No of Doors	5
Body Type	SUV	Drive Train	All-Wheel-Drive permanent
Seat Colour		No of Seats	5
Seat Covering Name	Braun	Seat Covering	Leather
Charging Cables	OUC + Type 2	NEDC CO2 Rating (q/km)	37
Gearbox Type	Automatic		

### Vehicle History & Documents


Service Book Available	Present	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warranty			













Equipment

Tinted Glass	Traffic sign recognition	USB Socket	Alloys wheels
Android Auto	Apple CarPlay	Bluetooth telephone interface	Digital Radio
Front fog lamps	Heated wing mirrors	Remote adjusting wing mirrors	Reversing Camera
Satellite navigation	Stability control	Distance warning system	Electrically folding wing mirrors
Emergency brake assist	Lane assist	LED Headlamps	Rear parking sensors
Tow ball	Trip Computer	Airbag Status	Ambient lighting
Anti-lock braking	Blind spot assist	Cruise control	Digital dashboard
Front parking sensors	Parking Assistance	Remote central locking	Roof rails
Split folding rear seats	Central locking	Electrically adjustable seats	Electric tailgate
Keyless Entry	Leather steering wheel	Radio	Rear sunblind

Equipment Details

Tow Ball Type	Electronic	Air Conditioning	Three Zone Climate Control
Alloy Wheel Size	20	Seat Heating	Front


Wheels & Tyres

Left Rear Tyre Depth	6	Right Front Tyre Depth	6
Left Front Tyre Depth	6	Right Rear Tyre Depth	6



Cosmetic Damage

10 Schäden



0 Schäden




	Component	Damage	Comments
1	Bumper / Front	Paint / Stone Chip	
2	Roof	Bodywork / Dent / Dent	
3	Rim / Back Left	Out of Bodywork / Scratch	
4	Bumper / Back	Paint / Scratch / Scuff	
5	Tailgate	Paint / Stone Chip	
6	Bumper / Back	Paint / Scratch / Scuff	
7	Wing Stick / Back Right	Paint / Scratch / Scuff	
8	Rim / Back Right	Out of Bodywork / Scratch	
9	Door / Front Right	Bodywork / Dent / Dent	
10	Rim / Front Right	Out of Bodywork / Scratch	



1. Bumper / Front  
Paint / Stone Chip -



2. Roof  
Bodywork / Dent / Dent -



3. Rim / Back Left  
Out of Bodywork / Scratch -



4. Bumper / Back  
Paint / Scratch / Scuff -



5. Tailgate  
Paint / Stone Chip -



6. Bumper / Back  
Paint / Scratch / Scuff -





7. Wing Stick / Back Right  
Paint / Scratch / Scuff -



8. Rim / Back Right  
Out of Bodywork / Scratch -



9. Door / Front Right  
Bodywork / Dent / Dent -



10. Rim / Front Right  
Out of Bodywork / Scratch -

## Mechanical Condition

### Equipments Test

Central Locking	✓	Electric Windows	✓
Navigation System	✓	Audio Equipment	✓
AC / Heating System	✓	Main & Spare Keys Functioning	✓
Parking Sensors / Cameras Functioning	✓	Other Equipments	✓

### Control Lights

ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Airbag Warning Light	✓	Oil Pressure Warning Light	✓
Brake Warning Light	✓	Power Steering Warning Light	✓
Alternator / Battery	✓	All - wheel Drive	✓
No Dashboard Lights	✓	Display Defect	✓
Service Light	✓	Tire Pressure Monitoring System	✓

### Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

### Gearbox

Gear Box	✓
----------	---

### Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---

### Hybrid/EV

Charge Lead Condition	✓	Charge Port Condition	✓
Hybrid System Fault	✓		



Test Drive Inspection

Steering Wheel			
Steering   Noise / Anomaly		✔	
Engine			
Engine Noise	✔	The Gears Scratch / Skip / Abnormal Operation	✔
Fume Quantity	✔	Power Loss	✔
Brake			
Brake System Anomaly		✔	
General			
Test Driven Status		Not Performed	
✔ <i>No troubles detected, good condition or correct tests, according to vehicle age and mileage</i>			
❗ <i>Damages or malfunction detected that requires repairs by the buyer</i>			
NA <i>Not applicable</i>			
= <i>Not tested</i>			

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)