



BMW X5: 1YWH981			
Vinnumber:	WBATA610809F15917	Versionname:	xDrive45e (155kW)
First Registrationdate:	11/01/2021	Fiscalpower:	
Expertise Mileage:	87338	Power Kw:	235
Bodytype:		Body colour:	Blue
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	2207
Fueltype:	Hybrid Petrol		
Maintenance:	NOT OK		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	No		

Options			
Number of keys total:	2	Seats electric F L:	
Cruise Control:		Seats electric F R:	
Steering wheel multifunctional:		Luggage cover:	
Seats F heated:		Front parking sensors:	
Radio multimedia:		Rear parking sensors:	
Type of headlighting:	Headlighting LED	Type of Tow bar:	No Tow bar
Type of GPS:	GPS big screen color		
Type of Lining:	Lining artificial leather		
Type of climate control:	Autom climate control		

Limited Technical Inspection

Degree of wear

265/60/19/110 H				
Winter tyres:	Fr.L.	Pirelli: 5 mm	Fr.R.	Pirelli: 5 mm
	Re.L.	Pirelli: 5 mm	Re.R.	Pirelli: 5 mm
Tyre profile depth FL	5.0			
Tyre profile depth FR	5.0			
Tyre profile depth RL	5.0			
Tyre profile depth RR	5.0			
Tyre size FL	265/60 R 19 110 H			
Tyre size FR	265/60 R 19 110 H			
Tyre size RL	265/60 R 19 110 H			
Tyre size RR	265/60 R 19 110 H			
Tyre type FL	Winte			
Tyre type FR	Winte			
Tyre type RL	Winte			
Tyre type RR	Winte			
Tyre make FL	264			
Tyre make FR	264			
Tyre make RL	264			
Tyre make RR	264			

Assistance equipment

Number of charging cables (normal):	2
Number of charging cables (rapid charge):	1

Total cost ex VAT	1913,99
Registration document, Missing, Replace	187,67



Service, Maintenance, Check

0,00



Bumper F, Scratch(es), Repair and paint (complete)

346,88



Alloy rim RL, Scratch(es), Repair and paint (complete)

129,66



Door RL, Scratch(es), Acceptable

0,00



Door FL, Scratch(es), Acceptable

0,00



Alloy rim FL, Scratch(es), Acceptable

0,00



Bumper moulding R, Scratch(es), Smart repair

113,74



Bumper R, Scratch(es), Repair and paint (complete)

346,88



Wing trim RR, Scratch(es), Replace	154,73
------------------------------------	--------



Alloy rim RR, Scratch(es), Repair and paint (complete)	129,66
--	--------



Wing RR, Chemical polution, Repair and paint (complete)	504,77
---	--------

