



BMW X5: N028NZ

Vinnumber:	WBATA610909J87307	Versionname:	X5 xDrive 45eA 290kW
First Registrationdate:	30/11/2021	Fiscalpower:	
Expertise Mileage:	180908	Power Kw:	210
Bodytype:		Body colour	Carbonschwarz Metallic
Gearbox:	Automatic	Paint type	Metallic
Transmission:	4 Wheel-drive	Type of rims (mounted)	Aluminium
Fueltype:	Hybrid Petrol	Parking lot	278
Number of seats	5		
Type of rims (mounted)	Aluminium		
Maintenance needed	No		

Options

Number of keys total	2	Telephone equipment
GPS		Lining leather
Autom climate control		Central consol F
Windows electric F		Luggage cover
		Headlights Xenon/LED/Laser
		Front parking sensors
		Rear parking sensors
		Hook

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	275 / 45 / 20 / 110 / Y / Aluminium	4,0 mm	Pirelli	Summer
	Right	275 / 45 / 20 / 110 / Y / Aluminium	3,1 mm	Pirelli	Summer
Rear	Left	305 / 40 / 20 / 112 / Y / Aluminium	5,9 mm	Pirelli	Summer
	Right	305 / 40 / 20 / 112 / Y / Aluminium	5,8 mm	Pirelli	Summer

Assistance equipment

Number of charging cables (normal)	1
Number of charging cables (rapid charge)	1

Door FL, Scratch(es), Repair and paint (complete)




Wing FL, Scratch(es), Repair and paint (complete)






Wing RL, Scratch(es), Repair and paint (complete)



Wheel arch cover RL, Scratch(es), Replace



Outer sill L, Scratch(es), Repair and paint (complete)



Outer door handle FL, Scratch(es), Repair and paint (complete)



Outer door handle RL, Scratch(es), Repair and paint (complete)



Door RL, Scratch(es), Repair and paint (complete)






Bonnet, Stone chip(s), Repair and paint (complete)



Bumper F, Scratch(es), Repair and paint (complete)



Door FR, Scratch(es), Repair and paint (complete)



Outside rear-view mirror housing R, Scratch(es), Replace and paint




Door RR, Scratch(es), Repair and paint (complete)



Wing RR, Scratch(es), Repair and paint (complete)



Outer sill R, Scratch(es), Repair and paint (complete)



Bumper RM, Dent(s) and scratch(es), Replace and paint





Tailgate / Boot, Scratch(es), Repair and paint (complete)



Bumper R, Scratch(es), Repair and paint (complete)



Bumper moulding R, Scratch(es), Replace and paint



Bodywork, Paint measurement, Acceptable



Roof, Dent(s), Paintless dent repair



