



BMW X3 (KKL): 1WSK760

Vinnumber:	WBAUZ15050NA92196	Versionname:	X3 (G01) 2.0d sDrive 18d 136pk/cv 5p Aut.
First Registrationdate:	29/08/2019	Fiscalpower:	
Expertise Mileage:	166703	Power Kw:	100
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:			
Maintenance	OK		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	No Tow bar
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

	245/45/20/103 V			
Winter tyres:	Fr.L.	Pirelli: 3 mm	Fr.R.	Pirelli: 3 mm
	Re.L.	Continental: 7 mm	Re.R.	Continental: 7 mm
Tyre profile depth FL				3.0
Tyre profile depth FR				3.0
Tyre profile depth RL				7.0
Tyre profile depth RR				7.0
Tyre size FL				245/45 R 20 103 V
Tyre size FR				245/45 R 20 103 V
Tyre size RL				275/40 R 20 106 V
Tyre size RR				275/40 R 20 106 V
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				264
Tyre make FR				264
Tyre make RL				256
Tyre make RR				256

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Bumper F, Dent(s) and scratch(es), Repair and paint (complete)





Alloy rim RL polished, Scratch(es), Repair and paint (complete)



Door FL, Scratch(es), Acceptable



Alloy rim FL polished, Scratch(es), Acceptable



Door RL, Dent(s) and scratch(es), Repair and paint (complete)



Wing RL, Scratch(es), Repair and paint (complete)



Wing FL, Scratch(es), Acceptable



Boot lid covering R, Scratch(es), Smart repair



Tailgate / Boot, Dent(s) and scratch(es), Repair and paint (complete)





Bumper R, Scratch(es), Repair and paint (complete)



Bumper moulding R, Scratch(es), Repair and paint (complete)



Wheel aperture RR, Dent(s) and scratch(es), Spot repair



Alloy rim FR polished, Scratch(es), Repair and paint (complete)



Wing trim FR, Scratch(es), Acceptable



Alloy rim RR polished, Scratch(es), Repair and paint (complete)





Door RR, Dent(s) and scratch(es), Acceptable



Door FR, Scratch(es), Repair and paint (complete)



Bodywork, Paint measurement, Acceptable

